

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW89	ARRI891	CM	D3.0,D2.0,D1.1	Arris	DG860	8.0.4A	1	X	10/100/1000 Base-T (4)		
CW89	ARRI892	CM	D3.0,D2.0,D1.1	Arris	CM820A	8.0.4A	1	X	10/100/1000 Base-T (1)		
CW89	ARRI893	CM	D3.0,D2.0,D1.1	Arris	TM822G	8.0.4A	2	X	10/100/1000 Base-T (1)		
CW89	CVTG891	CM	D3.0,D2.0,D1.1	Cisco	DPC3828	dpc3828-v302r125561	1.0	X	10/100/1000 Base-T (4), 802.11N		
CW88	ARRI881	CM	D3.0,D2.0,D1.1	Arris	TG862G	8.0.4	5	X	10/100/1000 Base-T (4)		
CW88	CVTG881	CM	D2.0,D1.1	Cisco	DPC2325R2	dpc2300-v202r124482	1.0		10/100 Base-T(4), 802.11N		
CW88	CVTG882	EMTA	P1.5,P1.0,D2.0,D1.1	Cisco	DPC2425R2	dpc2400-v202r124482	1.0		10/100 Base-T(4), 802.11N, RJ-11 (2)		
CW88	HITR881	CM	D3.0,D2.0,D1.1	Hitron	CGN	3.1.4.46	1A	X	10/100/1000 Base-T (4)		
CW88	PACE881	DSG+ECM	DSG,D2.0,D1.1	Pace Micro Technology	RNG150N-P2	2.122.2.16	v1.0		10/100/1000 Base-T (1)		Verified for Interoperability
CW88	UBEE881	CM	D3.0,D2.0,D1.1	Ubee Interactive	DDW3630	8.12.1000	4.37.1	X	10/100/1000 Base-T (4), 802.11N		
CW86	CHEE861	eCMM	D3.0,D2.0,D1.1	Cheetah Technologies	66950-1000	1.0.0 Build 5	A	X	10/100/1000 Base-T (1)		
CW85	CVTG851	EMTA	P1.5,P1.0,D2.0,D1.1	Cisco	DPC2420R2	dpc2400-v202r124482	1.0		10/100 Base-T (1), 802.11N, RJ-11 (2)		
CW85	CVTG852	CM	D3.0,D2.0,D1.1	Cisco	DPC3827	dpc3827-v302r125532	1.0	X	10/100/1000 Base-T (4), 802.11N		
CW85	CVTG853	CM	D2.0,D1.1	Cisco	DPC2320	dpc2300-v202r124482	1.0		10/100 Base-T (1), 802.11N		
CW85	MOTO851	CM	D3.0,D2.0,D1.1	Motorola	SBG6580	SBG6580-3.1.0.0-CW-02-SH	2	X	10/100/1000 Base-T (4)		
CW85	NTGR851	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Netgear	CGD3700B	5.2.2 beta7	1.00	X	10/100/1000 Base-T (4), RJ-11 (2)		
CW85	UBEE851	CM	D3.0,D2.0,D1.1	Ubee Interactive	DDM3520	3.1.2.34	1.67	X	10/100/1000 Base-T (1)		
CW84	MOTO841	EMTA	P1.5,P1.0,D2.0,D1.1	Motorola	SVG1202	SVG1202-2.0.0.0-CW-03-LTSH	1.0		10/100/1000 Base-T (1)		
CW84	SMCN841	CM	D3.0,D2.0,D1.1	SMC	SMCD3GN3	3.1.1.29	1A	X	10/100/1000 Base-T (4)		
CW84	TECH841	EMTA	P1.5,P1.0,D2.0,D1.1	Technicolor	TC7110	STC7.00.01	1.0		10/100 Base-T, 802.11N		
CW83	DLIN831	CM	D3.0,D2.0,D1.1	Dlink	DCM-301	518	A0	X	10/100/1000 Base-T (1)	CAST791	
CW83	MOTO831	CM	D3.0,D2.0,D1.1	Motorola	SB6141	3.1.103.32	7.0	X	10/100/1000 Base-T (1)		
CW83	NTGR831	CM	D3.0,D2.0,D1.1	Netgear	CGD3700T	V1.00.04	1.11	X	10/100/1000 Base-T (4)		
CW83	ZOOM831	CM	D3.0,D2.0,D1.1	Zoom	5350	5.1.6beta3	V1.0	X	10/100/1000 Base-T (1)	SMCN742	
CW83	ZOOM832	CM	D3.0,D2.0,D1.1	Zoom	5341J	518	A0	X	10/100/1000 Base-T (1)	CAST791	
CW82	BNMX821	CM	D3.0,D2.0,D1.1	Broad Net Mux Corp.	BCW620	518	A0	X	10/100/1000 Base-T (1)	CAST791	
CW82	BNMX822	CM	D3.0,D2.0,D1.1	Broad Net Mux Corp.	BCW610	2.381.51x.001	A2	X	10/100/1000 Base-T (1)	CAST711	
CW82	CAST821	EMTA	P1.5,P1.0,D2.0,D1.1	Castlenet	Netmaster CBW-700V	4.4.7	V1.0		10/100 Base-T (4), 802.11N		
CW82	CVTG821	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Cisco	DRG7908	drg7908-P15-14-v302r12111a	1.0	X	10/100/1000 Base-T (1)		
CW81	CVTG812	DSG+ECM	DSG,D2.0,D1.1	Cisco	4700	1.0.9000.0106	1.3	X	10/100/1000 Base-T (1)		Verified for Interoperability
CW80	CVTG801	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Cisco	DPC3208	d3200-P15-14-v302r125521a	1.0	X	10/100/1000 Base-T (1)		
CW80	HITR801	CM	D3.0,D2.0,D1.1	Hitron	CDA-30360	3.1.0.15a	1A	X	10/100/1000 Base-T (1)		
CW80	HUAW801	CM	D3.0,D2.0,D1.1	Huawei	MT130U	V100R001C01B030	VER.A	X	10/100/1000 Base-T (1)		
CW80	NTGR801	CM	D2.0,D1.1	Netgear	CG2003D	4.4.6R01.1	1.0		10/100 Base-T (4)		
CW80	RUCK801	eCMM	D3.0,D2.0,D1.1	Ruckus Wireless	CMM67	V92000	V1.0	X	10/100/1000 Base-T (1)		
CW80	RUCK802	eCMM-Based	D3.0,D2.0,D1.1	Ruckus Wireless	ZF7761CM	V92000	V1.0	X	100 Base-T (1), 802.11N		
CW79	CAST791	CM	D3.0,D2.0,D1.1	Castlenet	CBC382D1	518	A0	X	10/100/1000 Base-T (1)		
CW79	CVTG791	DSG+ECM	DSG,D2.0,D1.1	Cisco	8700	1.0.9000.0104	1.5	X	10/100/1000 Base-T (1)		Verified for Interoperability
CW79	MOTO791	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Motorola	SVG7540	73.0.1.16	HW_REV: 1.0	X	10/100/1000 Base-T (4), RJ-11 (2)		
CW79	UBEE791	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Ubee Interactive	DVM3220	7.10.1001	2.62.1	X	10/100/1000 Base-T (1), RJ-11 (2)		
CW79	UBEE792	E-DVA	P2.0,D3.0,D2.0,D1.1	Ubee Interactive	DVW3213	9.5.4000	3.7.3	X	10/100/1000 Base-T (4), RJ-11 (2)		Basic Certification

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW78	ARRI781	CM	D3.0,D2.0,D1.1	Arris	DG950A	7.11.12	1	X			
CW78	UBEE781	CM	D3.0,D2.0,D1.1	Ubee Interactive	DDM3530	3.30.1000	1.50.1	X			
CW77	CVTG771	CM	D3.0,D2.0,D1.1	Cisco	DPC3008	dpc3008-v302r121007a	1.0	X			
CW77	HUAW771	CM	D2.0,D1.1	Huawei	MT120U	V100R001	V1.0				
CW77	THOM771	CM	D3.0,D2.0,D1.1	Technicolor	DCM476	STAC.00.00	2.0	X			Technicolor formerly known as Thomson
CW77	UBEE771	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Ubee Interactive	DVW3213	9.5.1000.3	3.7.3	X			
CW76	ARRI761	CM	D3.0,D2.0,D1.1	Arris	TG852G	7.3.33A	1	X			
CW76	CVTG761	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Cisco	DPQ3925	DPQ3925-P15-14-v302r121003a	1.0	X			
CW76	MOTO761	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Motorola	SBV6240	82.0.2.34	4.0	X			
CW76	MOTO762	E-DVA	P2.0,D2.0,D1.1	Motorola	SBV5222	SBV5222-2.2.0.5-CWT76-NOSH	1.0				Basic Certification
CW76	NTGR761	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Netgear	CG3000X	4.5.14	1.01	X			
CW76	SMCN761	CM	D3.0,D2.0,D1.1	SMC	SMCD3CMB	0.01.00	1.0	X			
CW76	THOM761	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Technicolor	DHG576	STA7.00.00	2.0	X			Technicolor formerly known as Thomson
CW75	MOTO751	CM	D3.0,D2.0,D1.1	Motorola	SB6121	2.0.2.33	5.0	X			
CW75	PACE751	DSG+ECM	DSG,D2.0,D1.1	Pace Micro Technology	RNG200N	2.2.2mp2	V1.0				Verified for Interoperability
CW75	PACE752	DSG+ECM	DSG,D2.0,D1.1	Pace Micro Technology	RNG150N	2.2.2mp2	V1.0				Verified for Interoperability
CW74	CVTG741	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Cisco	DPQ3925	DPQ3925-P15-14-v302r121003a	1.0	X			
CW74	CVTG742	CM	D3.0,D2.0,D1.1	Cisco	DPC3825	dpc3825-v302r121003a	1.0	X			
CW74	INNO741	eCMM	P1.5,P1.0,D2.0,D1.1	Innomedia	6528-LC	1.1.13 Fri Mar 5 19:33:30 2010	10.12.0.1				
CW74	SMCN741	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	SMC	SMCD3GNV	2.0.0.26	1A	X			
CW74	SMCN742	CM	D3.0,D2.0,D1.1	SMC	SMCD3GNB	5.1.6beta3	V1.0	X			
CW73	CVTG731	CM	D3.0,D2.0,D1.1	Cisco	DPQ3825	dpq3825-v302r171002	1.0	X			
CW73	PANA731	DSG+ECM	DSG,D2.0,D1.1	Panasonic	PCH2200	2.2.2	V0.90				Verified for Interoperability
CW73	UBEE731	CM	D2.0,D1.1	Ubee Interactive	DDW2610	5.115.1000	4.33.1				
CW73	ZOOM731	CM	D3.0,D2.0,D1.1	Zoom	5341	1.2.1.34	1A	X		HITR661	
CW72	INNO721	eCMM	P1.5,P1.0,D2.0,D1.1	Innomedia	6528-LC	1.1.12 Thu Nov 5 16:18:15 2009	10.12.0.1				
CW72	INNO722	eCMM-Based	P1.5,P1.0,D2.0,D1.1	Innomedia	eMTA 6528	1.1.12 Thu Nov 5 16:18:15 2009	10.12.0.1				Verified for Interoperability
CW72	NTGR721	EMTA	P1.5,P1.0,D2.0,D1.1	Netgear	CG2000	4.5.11	1.04				
CW72	NTGR722	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Netgear	CVD31XB	4.5.11	1.05	X			
CW72	SMCN721	CM	D3.0,D2.0,D1.1	SMC	SMCD3GN2	1.5.0.12	1A	X			
CW72	THOM721	CM	D3.0,D2.0,D1.1	Technicolor	DWG875	STB1.00.01	1.0	X			Technicolor formerly known as Thomson
CW71	AMCO711	CM	D2.0,D1.1	AM Communications	DSM3	4.5.9.0_01.00-NA	2.0				
CW71	ARRI711	EMTA	P1.5,P1.0,D2.0,D1.1	Arris	TM632A	6.10.4	1				
CW71	CAST711	CM	D3.0,D2.0,D1.1	Castlenet	CBC-381	2.381.51x.001	A2	X			
CW71	MOTO712	CM	D3.0,D2.0,D1.1	Motorola	SBG6580	SBG6580-3.1.0.0-CW-02-SH	Rev. 1	X			
CW71	NTGR711	CM	D3.0,D2.0,D1.1	Netgear	CG3200D	V1.3.1.0	1.11	X			
CW71	NTGR712	CM	D3.0,D2.0,D1.1	Netgear	CMD31B	5.1.4	1.00	X			
CW71	SMCN711	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	SMC	SMCD3USG	1.5.0.12	1.0	X			
CW71	UBEE711	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Ubee Interactive	DVW3200	9.2.2000	3.7.1	X			
CW70	CVTG701	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Cisco	DPQ3212	DPQ3212-P15-15-v302r12906	1.0	X			
CW70	DLIN701	CM	D3.0,D2.0,D1.1	Dlink	DCM-301	5.1.4	A1	X			
CW70	JNPR701	eCMM	D3.0,D2.0,D1.1	Juniper Networks	ECM3100-JU	1.4.0.11	1.1	X			
CW70	MOTO701	CM	D3.0,D2.0,D1.1	Motorola	SB6180	SB6180-3.5.0.0-CW-70-NOSH	Rev1	X			
CW70	MOTO702	EMTA	P1.5,P1.0,D2.0,D1.1	Motorola	SVG2501	SVG2501-2.0.0.0-CW-04-LTSH	Rev. 1				
CW70	NTGR701	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Netgear	CG3000	4.5.9beta6	1.03	X			

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW70	THOM701	CM	D3.0,D2.0,D1.1	Technicolor	DCW775	STB5.01.01	1.0	X			Technicolor formerly known as Thomson
CW70	UBEE701	CM	D3.0,D2.0,D1.1	Ubee Interactive	DDW3610	5.113.2000	4.31	X			
CW68	MOTO682	EMTA	P1.5,P1.0,D2.0,D1.1	Motorola	SBV5122	SBV5122-2.22.2.2-CWT04-SHPC	2				
CW68	MOTO683	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Motorola	SBV6120	1.1.2.47	Rev 1	X			
CW68	MOTO684	CM	D2.0,D1.1	Motorola	SBG941	SBG941-2.1.0.0-CW-01-NOSH	1				
CW67	ARRI671	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Arris	TM702G	7.1.12	7.7	X			
CW67	ARRI672	CM	D3.0,D2.0,D1.1	Arris	WBM750A	3.2.15C	5	X			
CW67	MOTO671	EMTA	P1.5,P1.0,D2.0,D1.1	Motorola	SVG1501U	2.0.0.0	Rev. 1				
CW67	MOTO672	CM	D3.0,D2.0,D1.1	Motorola	SB6120	1.2.2.45	3.0	X			
CW67	PACE671	DSG+ECM	DSG,D2.0,D1.1	Pace Micro Technology	RNG110	4.4.3alpha5	V1.0				Verified for Interoperability
CW67	SMCN671	CM	D3.0,D2.0,D1.1	SMC	SMCD3G	1.2.2.45	1.01	X			
CW67	UBEE671	EMTA	P1.5,P1.0,D2.0,D1.1	Ubee Interactive	DVW2200	6.22.1000	3.6.1				
CW67	UBEE672	CM	D3.0,D2.0,D1.1	Ubee Interactive	DDW3600	8.2.1000	4.29	X			
CW66	AMBI661	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Ambit	DVM3210	1.0.0.1	2.41	X			
CW66	CVTG661	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Cisco	DPQ3202	dpq3202-P15-15-v303r22903	2.0	X			
CW66	HITR661	CM	D3.0,D2.0,D1.1	Hitron	BRG-35503	1.2.1.34	1A	X			
CW66	MOTO661	CM	D2.0,D1.1	Motorola	SB5101N	SB5101NU-2.1.0.0-CW-04-NOSH	1.0				
CW66	MOTO662	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Motorola	SBV6220	1.1.1.29	2	X			
CW65	AMBI651	CM	D3.0,D2.0,D1.1	Ambit	DDM35000	3.19.1001	1.42	X			
CW65	AMBI652	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Ambit	DVM32000	3.21.1001	2.55	X			
CW65	AMBI653	CM	D3.0,D2.0,D1.1	Ambit	U10C035	1.0.0.2	1.0	X			
CW65	CVTG651	CM	D2.0,D1.1	Cisco	DPC2100R3	dpc2100r3-v202r12901	3.0				
CW65	CVTG652	CM	D3.0,D2.0,D1.1	Cisco	DPC3000	dpc3000-v303r22901	2.0	X			
CW65	CVTG653	CM	D3.0,D2.0,D1.1	Cisco	DPC3010	v302r22901	1.0	X			
CW65	DLIN651	EMTA	P1.5,P1.0,D2.0,D1.1	Dlink	DCM-604	81.700V.4216.729.001	1.0			CAST641	
CW65	MOTO651	CM	D2.0,D1.1	Motorola	SBG901	SBG901N-2.1.0.0-CW-01-NOSH	1.0				
CW65	NTGR651	CM	D3.0,D2.0,D1.1	Netgear	CMD31T	1.2.0.23	1.02A	X			
CW65	NTGR652	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Netgear	CVD31XT	1.1.0.18	1.04	X			
CW65	SMCN651	CM	D3.0,D2.0,D1.1	SMC	SMCD3CM	1.2.0.23	1.02	X			
CW65	THOM651	CM	D3.0,D2.0,D1.1	Technicolor	DCM475	STAC.01.00	1.0	X			Technicolor formerly known as Thomson
CW65	THOM652	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Technicolor	DHG575	STA7.01.00	1.0	X			Technicolor formerly known as Thomson
CW65	ZYXE651	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Zyxel	P-2910	1.1.0.18	94.4	X			
CW64	2CASA641	CMTS+PC	P1.5,P1.0,D3.0,D2.0,D1.1	Casa Systems	C10200	5.1.1	1.1	X			
CW64	CAST641	EMTA	P1.5,P1.0,D2.0,D1.1	Castlenet	Netmaster CBW-700V	81.700V.4216.729.001	V1.0				
CW64	CVTG641	DSG+ECM	DSG,D2.0,D1.1	Cisco	8600	1.5.7000.0105	1.2				Verified for Interoperability
CW64	CVTG643	CM	D2.0,D1.1	Cisco	DPC2325	dpc2325-v202r12811	1.0				
CW64	CVTG644	CM	D2.0,D1.1	Cisco	DPQ2160	dpq2160-v202r12811	2.0				
CW64	CVTG645	CM	D3.0,D2.0,D1.1	Cisco	DPC3000	dpc3000-v303r12810	1.1	X			
CW64	NTGR641	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Netgear	CVD31XT	1.0.2.22	1.04	X			
CW64	SMCN641	CM	D3.0,D2.0,D1.1	SMC	SMCD3G	1.1.2.21	1.01	X			
CW64	CVTG642	EMTA	P1.5,P1.0,D2.0,D1.1	Scientific Atlanta	DPQ2425	v202r12811	1.0				
CW64	THOM641	EMTA	P1.5,P1.0,D2.0,D1.1	Technicolor	DHG546	STA5.01.00	1.0				Technicolor formerly known as Thomson
CW63	AMBI631	CM	D3.0,D2.0,D1.1	Ambit	U10C035	1.0.0.1	1.0	X			
CW63	ARRI631	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Arris	TM702G	7.1.10	4.0	X			

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW63	ARRI632	CM	D3.0,D2.0,D1.1	Arris	WBM750A	3.1.6	1.0	X			
CW63	HITR631	CM	D3.0,D2.0,D1.1	Hitron	BRG-35503	1.1.0.19	1.01	X			
CW63	MOTO631	CM	D3.0,D2.0,D1.1	Motorola	SB6120	1.1.0.19	1.0	X			
CW63	MOTO632	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Motorola	SBV6220	1.0.0.21	1.0	X			
CW63	NTGR631	CM	D3.0,D2.0,D1.1	Netgear	CMD31T	1.1.0.19R01	1.02	X			
CW63	SMCN631	CM	D3.0,D2.0,D1.1	SMC	SMCD3CM	1.1.0.19	1.01	X			
CW63	SCIE631	DSG+ECM	DSG,D2.0,D1.1	Scientific Atlanta	1600	2.1.4000.0302	1.6				Verified for Interoperability
CW63	SCIE632	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Scientific Atlanta	DPQ3202	dpq3202-v303r22810	2.0	X			
CW63	SCIE633	CM	D3.0,D2.0,D1.1	Scientific Atlanta	DPC3000	dpc3000-v303r12810	2.0	X			
CW62	PANA621	DSG+ECM	DSG,D2.0,D1.1	Panasonic	TZ-PCH2180M	2.0.0	1.07				Verified for Interoperability
CW61	HITR611	CM	D3.0,D2.0,D1.1	Hitron	BRG-35503	1.0.2.31	1.1	X			
CW61	SCIE611	EMTA	P1.5,P1.0,D2.0,D1.1	Scientific Atlanta	DPQ2202	v202r1287	1.0				
CW60	NTGR601	CM	D2.0,D1.1	Netgear	CGD24G	V4.2.18.R01	1.0				
CW60	NTGR602	CM	D3.0,D2.0,D1.1	Netgear	CMD31T	1.0.0.27R01	1.02	X			
CW60	REMB601	EMTA	P1.5,P1.0,D2.0,D1.1	Rembrandt Technologies, LLC	REM-8200	23.0.0.12	72.2				
CW60	SCIE601	EMTA	P1.5,P1.0,D2.0,D1.1	Scientific Atlanta	DRG2800	v2.0.2r1285	1.0				
CW60	SCIE602	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Scientific Atlanta	DPQ3202	dpq3202-v303r2285	2.0	X			
CW60	ZYXE601	EMTA	P1.5,P1.0,D2.0,D1.1	Zyxel	P2900	22.2.2.22	72.2				
CW59	AMBI591	CM	D2.0,D1.1	Ambit	U10C037	2.93.9059	1.0				
CW59	ARRI591	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Arris	TM702G	7.1.3	4.0	X			
CW59	ARRI592	CM	D3.0,D2.0,D1.1	Arris	WBM750A	7.0.17	1.0	X			
CW59	MOTO591	EMTA	P1.5,P1.0,D3.0,D2.0,D1.1	Motorola	SBV6220	0.5.0.43	1.0	X			
CW59	SCIE591	CM	D2.0,D1.1	Scientific Atlanta	DPQ2160	dpq2160-v202r1582	1.0				
CW58	AMBI581	CM	D3.0,D2.0,D1.1	Ambit	U10C035	1.0.0.0	1.0	X			
CW58	2ARRI581	CMTS	D3.0,D2.0,D1.1	Arris	C4-CMTS-2100-1	CMTS_V07.00.03.32	3.0	X			Bronze Qualification - Expired
CW58	ARRI581	CM	D3.0,D2.0,D1.1	Arris	TM702G	7.0.12	1.0	X			
CW58	2CASA581	CMTS	D3.0,D2.0,D1.1	Casa Systems	C2200 CMTS	5.0.16	1.1	X			Full Qualification
CW58	2CASA582	CMTS	D3.0,D2.0,D1.1	Casa Systems	C3200 CMTS	5.0.16	3.0.0	X			Full Qualification
CW58	2CISC581	CMTS	D3.0,D2.0,D1.1	Cisco	uBR10012	Ubr10k2-k9p6u2_CW-mz.122-BRONZE_CW58_FINAL.080218	V01	X			Bronze Qualification - Expired
CW58	2MOTO581	CMTS	D3.0,D2.0,D1.1	Motorola	BSR 64000	5.1.0T06P19.HXX.KRAU	CHS-0009-01	X			Bronze Qualification - Expired
CW58	MOTO581	CM	D3.0,D2.0,D1.1	Motorola	SB6120	1.0.0.20	1.0	X			
CW58	MOTO582	CM	D3.0,D2.0,D1.1	Motorola	SBV6220	1.0.0.20	1.0	X			
CW58	SMCN581	CM	D3.0,D2.0,D1.1	SMC	SMCD3CM	1.1.3	1.0	X			
CW58	SCIE581	DSG+ECM	DSG,D2.0,D1.1	Scientific Atlanta	1500	2.1.1000.0108	1.1				Verified for Interoperability
CW58	SCIE582	CM	D3.0,D2.0,D1.1	Scientific Atlanta	DPC3000	dpc3000-v301r2382	1.0	X			
CW57	AMBI571	EMTA	P1.5,P1.0,D2.0,D1.1	Ambit	U10C034	4.97.1004	1.0				
CW57	THOM571	CM	D2.0,D1.1	Technicolor	DHG537	STA0.00.00	1.0				Technicolor formerly known as Thomson
CW57	THOM572	EMTA	P1.5,P1.0,D2.0,D1.1	Technicolor	ACG905	1.0.1	0				Technicolor formerly known as Thomson
CW56	2ARRI561	CMTS	D3.0,D2.0,D1.1	Arris	C4-CMTS-2100-1	CMTS_V07.00.00.79	3.0	X			Bronze Qualification - Expired
CW56	2CASA561	CMTS	D3.0,D2.0,D1.1	Casa Systems	C2200 CMTS	5.0.5	1.1	X			Silver Qualification
CW56	2CISC561	CMTS	D3.0,D2.0,D1.1	Cisco	uBR10012	UBR10K2-K9P6U2_CW-M	UBR10-MC5X20H-X rev v03	X			Bronze Qualification - Expired
CW56	MASP561	eCMM	D2.0,D1.1	Maspro	ACM6049-SC	2.46	1.13B				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW56	SCIE562	CM	D2.0,D1.1	Scientific Atlanta	DPC2160	dpc2160-v202r10711	1.0				
CW56	THOM561	EMTA	P1.5,P1.0,D2.0,D1.1	Technicolor	DHG536	ST75.01.00	1.0				Technicolor formerly known as Thomson
CW54	ARRI541	CM	D2.0,D1.1	Arris	TM602G	5.2.12A	02				
CW54	SCIE541	DSG+ECM	DSG,D2.0,D1.1	Scientific Atlanta	8501	1.5.1005.0304	1.4				Verified for Interoperability
CW54	TOLL541	eCMM	D2.0,D1.1	Tollgrade	CMD-CM	3.4.0 Build 3 CxC 3.9.17	1.0.0				
CW53	HITR531	EMTA	P1.5,P1.0,D2.0,D1.1	Hitron	BVG-3642	1.22.1.6	1A				
CW53	MOTO531	EMTA	P1.5,P1.0,D2.0,D1.1	Motorola	SVG2500	SVG2500N-2.3.1.7-ALPHA-00-	1				
CW52	OHWEI521	CMS	P1.0	Huawei	SOFTX3000	V50R601	OSTA				
CW52	REMB521	CM	D2.0,D1.1	Rembrandt Technologies, LLC	REM-8100	22.2.0.13	56.1				
CW52	SLNG521	CM	D2.0,D1.1	Sling Media	V-Modem007	22.2.0.13	54.7				
CW51	AMBI511	CM	D2.0,D1.1	Ambit	U10C023	2.93.9051	1.0				
CW51	MOTO512	EMTA	P1.5,P1.0,D2.0,D1.1	Motorola	SBV5322	SBV5322-2.22.2.0-CWT03-NOSH	1				
CW51	THOM511	CM	D2.0,D1.1	Technicolor	DCM465	ST95.01.00	1.0				Technicolor formerly known as Thomson
CW50	SCCOR501	Policy Server	PCMM	C-Cor	Not Applicable	1.2	Not Applicable				
CW50	SMCN501	EMTA	P1.5,P1.0,D2.0,D1.1	SMC	SMC8414WG	2.2.2.5	1.0				
CW49	MOTO491	EMTA	P1.5,P1.0,D2.0,D1.1	Motorola	SBV5222	SBV5222-2.22.2.0-CWT06-NOSH	1				
CW49	SCIE491	CM	D2.0,D1.1	Scientific Atlanta	DPC2505	dpc2505-v202r1071	1.0				
CW48	AMCO481	CM	D2.0,D1.1	AM Communications	Model 9362A	1.83	4.0				
CW48	CISC481	eCMM-Based	D2.0,D1.1	Cisco	CISCO815	2.103.1013	2.0				
CW48	CISC482	eCMM-Based	D2.0,D1.1	Cisco	Cisco IAD2431	2.103.1013	2.0				
CW48	LINK481	CM	D2.0,D1.1	Cisco-Linksys, LLC	CM100	0.0.6.13010	54.0				
CW47	MOTO471	CM	D2.0,D1.1	Motorola	SB5102	SB5102N-2.1.0.0-GA-07-NOSH	1				
CW46	ARRI461	CM	D2.0,D1.1	Arris	CM550A	6.1.2	08				
CW45	AMBI451	EMTA	P1.5,P1.0,D2.0,D1.1	Ambit	U10C021	4.90.1003	2.31				
CW45	CISC451	eCMM	D2.0,D1.1	Cisco	HWIC-CABLE-D-2	2.103.1013	2.0				
CW45	CISC452	eCMM-Based	D2.0,D1.1	Cisco	CISCO1841	2.103.1013	2.0				This device was certified as an eCMM-based device with the CISC451 qualified eCMM.
CW45	MOTO451	DSG+ECM	DSG,D2.0,D1.1	Motorola	DCT3412/2305	0.1.4.7-SH	P3				Verified for Interoperability
CW45	SCIE451	Embedded PS	C1.1,D2.0,D1.1	Scientific Atlanta	DPR2325R3	dpr2325r3-v202r1264	3.0				
CW45	5SIEM451	Policy Server	PCMM	Siemens	Primergy TX300 S2	pcs-2.0-CertCW45_08	Primergy TX300 S2				
CW45	15SYMM451	DTIS	M-CMTS	Symmetricom	990-93105-01	IMC-0.9.5 IOC-0.5.30	A				
CW45	THOM451	CM	D2.0,D1.1	Technicolor	DCM425	ST52.05.00	4.1				Technicolor formerly known as Thomson
CW45	THOM452	EMTA	P1.5,P1.0,D2.0,D1.1	Technicolor	DHG535	ST70.02.01	1.1				Technicolor formerly known as Thomson
CW43	AMBI431	CM+MTA+PS	C1.1,P1.5,P1.0,D2.0,D1.1	Ambit	U10C022	7.10.1006	2.30				
CW43	SCIE431	EMTA	P1.0,D2.0,D1.1	Scientific Atlanta	DPC2203	v2.0.2r1263	1.1				
CW42	2CISC421	CMTS+DSG	DSG,D1.1	Cisco	uBR7246 VXR/MC28U	12.3(17a)BCc	MC28U:Rev 6.5				
CW42	LINK421	EMTA	P1.5,P1.0,D2.0,D1.1	Cisco-Linksys, LLC	CMP300B2	2.4.11.13010	58.0				
CW42	2MOTO421	CMTS	D2.0,D1.1	Motorola	BSR 2000	1.0.0T01P24.TRAU	520025-001-00 Rev 4				
CW42	TOLL421	EMTA	P1.0,D2.0,D1.1	Tollgrade	CMD-P	3.0.6 Build 2 CxC 3.9.7	1.0.0				Verified for Interoperability
CW42	TOLL422	CM	D2.0,D1.1	Tollgrade	CMD-E	3.0.6 Build 2 CxC 3.9.7	1.0.0				
CW41	LINK412	CM	D2.0,D1.1	Cisco-Linksys, LLC	BEFCMU10 ver. 6	0.0.6.13010	54.0				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW41	NTGR411	EMTA	P1.5,P1.0,D2.0,D1.1	Netgear	EM612	3.9.4.4R01	1.01				
CW41	PACE411	DSG+ECM	DSG,D1.1	Pace Micro Technology	TDC575D	1.1.1q001	V1.0				Verified for Interoperability
CW41	SCIE411	Embedded PS	C1.1,D2.0,D1.1	Scientific Atlanta	DPR2320	dpr2320r2-v202r1261	2.0				
CW41	SCIE412	CM+MTA+PS	C1.1,P1.0,D2.0,D1.1	Scientific Atlanta	DPC2434	dpc2434-v202r1261	1.0				
CW41	THOM411	Embedded PS	C1.1,D2.0,D1.1	Technicolor	DCW725	ST5A.07.00	5.0				Technicolor formerly known as Thomson
CW41	THOM412	CM+MTA+PS	C1.1,P1.5,P1.0,D2.0,D1.1	Technicolor	DWG855	ST80.01.00	2.0				Technicolor formerly known as Thomson
CW40	AMCO401	CM	D2.0,D1.1	AM Communications	Model 9360	1.0	5				
CW40	ATYT401	eCMM	D2.0,D1.1	ATI	CAFE 1.0	0.1.0.0	1.0				
CW40	ASUS401	EMTA	P1.0,D2.0,D1.1	Asustek	ACM6149	3.9.4R1000	1.10a				
CW40	2BIGB401	CMTS+MM	PCMM,D1.1	Bigband Networks	Cuda 12000	R6.0.0	Rev 4				
CW40	2CISC401	CMTS+MM	PCMM,D1.1	Cisco	uBR7246 VXR/MC28U	12.3(13a)BCc	MC28U:Rev 6.5				
CW40	LINK401	EMTA	P1.0,D2.0,D1.1	Cisco-Linksys, LLC	CMP200B2	2.0.3.9.6	1.0				
CW40	LINK402	CM+MTA+PS	C1.1,P1.0,D2.0,D1.1	Cisco-Linksys, LLC	WCGP200B2	2.0.3.9.6	1.0				
CW40	ELEC401	CM	D2.0,D1.1	Electroline	DHT-PS-NA-02	1.00	01				
CW40	5JNPR401	Policy Server	PCMM	Juniper Networks	SDX-S1-62300	6.2.0	N/A				
CW40	MOTO401	EMTA	P1.0,D2.0,D1.1	Motorola	SBV5221	SBV5221-2.17.8.6-SCM01-NOSH	1				
CW40	NTGR401	CM+MTA+PS	C1.1,P1.0,D2.0,D1.1	Netgear	CVG824G	3.9.4R0001	1.0.1				
CW40	SCIE401	CM	D2.0,D1.1	Scientific Atlanta	DPC2100R2	v2.0.2r1256	2.1				
CW40	4SIEM401	MG	P1.0	Siemens	hiG 1200	11.80.01.33	S50043-B1606-X-5				
CW40	THOM401	CM+MTA+PS	C1.1,P1.0,D2.0,D1.1	Technicolor	DWG855	ST78.01.00	1.0				Technicolor formerly known as Thomson
CW40	THOM402	EMTA	P1.0,D2.0,D1.1	Technicolor	DHG525	ST62.09.00	5.1				Technicolor formerly known as Thomson
CW40	TERA401	EMTA	P1.5,P1.0,D2.0,D1.1	Terayon	TJ955	17.2.0.7	58.0				
CW39	ASKE391	eCMM	D2.0,D1.1	Askey Computer Corp.	CMM300	2.0.3.8.5	1.0				
CW39	SMCN391	Embedded PS	C1.1,D2.0,D1.1	SMC	SMC8014WG-CHM	3.17.11	1.65				
CW39	WIDE391	CM	D2.0,D1.1	WideView Technology	WM-100	17.1.7.17	35.4.2				
CW38	ALPH381	CM	D2.0,D1.1	Alpha	Alpha CM-H	2.01.01AH1.0	1.0				
CW38	AMBI381	EMTA	P1.0,D2.0,D1.1	Ambit	U10C021	4.71.1001	2.31				
CW38	ARRI381	CM	D2.0,D1.1	Arris	TM502G	4.5.0	01				
CW38	LINK381	EMTA	P1.0,D2.0,D1.1	Cisco-Linksys, LLC	CMP300B	17.0.5.23	58.0				
CW38	LINK382	EMTA	P1.0,D2.0,D1.1	Cisco-Linksys, LLC	CMP200B	2.0.3.7.16	1.0				
CW38	LINK383	Embedded PS	C1.1,D2.0,D1.1	Cisco-Linksys, LLC	WCG104	2.0.3.7.16	2.0				
CW38	MOTO381	Embedded PS	C1.1,D2.0,D1.1	Motorola	SBG940	SBG940-2.1.1.1-SCM01-NOSH	1				
CW38	MOTO382	EMTA	P1.0,D2.0,D1.1	Motorola	SBV5200	SBV5200-2.1.3710.1-SCM00-SH	1				
CW38	MOTO383	EMTA	P1.0,D2.0,D1.1	Motorola	SBV5121	SBV5121-2.17.5.23-SCM01-NOSH	1				
CW38	PACE381	DSG+ECM	DSG,D2.0,D1.1	Pace Micro Technology	TDC775D	3.7.16001	V1.0				Verified for Interoperability
CW38	PACE382	EMTA	P1.0,D2.0,D1.1	Pace Micro Technology	DV315	v05.38.01	V1.0				
CW38	SCIE381	EMTA	P1.0,D2.0,D1.1	Scientific Atlanta	DPC2223	v2.0.2r1154	1.0				
CW38	SCIE382	EMTA	P1.0,D2.0,D1.1	Scientific Atlanta	DPC2203	v2.0.2r1254	1.0				
CW38	THOM381	EMTA	P1.0,D2.0,D1.1	Technicolor	DHG535	ST70.01.00	1.0				Technicolor formerly known as Thomson
CW38	THOM382	EMTA	P1.0,D2.0,D1.1	Technicolor	DHG525	ST62.08.00	5.0				Technicolor formerly known as Thomson
CW38	TOLL381	CM	D1.1	Tollgrade	1.0.0	1.0.2	1.0.0				
CW37	ASUS371	CM	D2.0,D1.1	Asustek	ACM6049EB	3.7.7	3.00				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW37	0NORT371	CMS	P1.1,P1.0	Genband	CS 2000 CMS	SN08.PSC	SN08.PHC				Genband formerly known as Nortel Networks
CW37	3NORT371	MGC	P1.1,P1.0	Genband	CS 2000 MGC	SN08.PSM	SN08.PHM				Genband formerly known as Nortel Networks
CW37	MOTO371	CM	D2.0,D1.1	Motorola	SB5121	SB5121-2.17.0.12-SCM01-NOSH	1.0				
CW37	4NUER371	MG	P1.1,P1.0	Nuera Communications	BTX-4K	1.1	A				
CW37	0SIEM371	CMS	P1.1,P1.0	Siemens	Surpass hiQ 8000	08.04.01.US.05	Sun Microsystems Netra 1400T				
CW37	3SIEM371	MGC	P1.1,P1.0	Siemens	Surpass hiQ 8000	08.04.01.US.05	Sun Microsystems Netra 1400T				
CW37	TURB371	CM	D2.0,D1.1	Turbocomm	EC420	17.0.1.11	29.2				
CW35	ARRI351	CM	D2.0,D1.1	Arris	TTM402P Phase 2	4.4.1	32				
CW35	TOSH351	CM	D2.0,D1.1	Toshiba	PCX3200	8.43.2	25.0.0				
CW35	TOSH352	CM	D1.1	Toshiba	PCX2000	2.1R.007	3.2.1				
CW34	AMBI341	EMTA	P1.0,D2.0,D1.1	Ambit	U10C017	4.36.1018	2.22				
CW34	2BIGB341	CMTS	D2.0,D1.1	Bigband Networks	Cuda 12000 (C12-DM2x8-2.0)	R6.0.0	Rev 4				
CW34	5CCOR341	Policy Server	PCMM	C-Cor	Not Applicable	1.0	Not Applicable				
CW34	5CABL341	Policy Server	PCMM	CableMatrix	ODSP	0.8.6	NA				
CW34	5CAMI341	Policy Server	PCMM	Camiant	CAMS-2275	2.0.0	Intel SR 1300 Server				
CW34	4CISC341	MG	P1.1,P1.0	Cisco	MGX8880	5.50	VXSM				
CW34	LINK341	EMTA	P1.0,D2.0,D1.1	Cisco-Linksys, LLC	CM2P2B	2.0.3.5.10	2.1				
CW34	LINK342	EMTA	P1.0,D2.0,D1.1	Cisco-Linksys, LLC	CG2P2WB	2.0.3.5.10	2.1				
CW34	2MOTO341	CMTS+MM	PCMM,D2.0,D1.1	Motorola	BSR 64000	4.1.0T08P10.12.KRAU	CHS-0009-01				
CW34	NTGR341	EMTA	P1.0,D2.0,D1.1	Netgear	CVG824G	3.5.8R01	1.00				
CW34	4NUER341	MG	P1.0	Nuera Communications	BTX-4K	1.1.0.4	A				
CW34	0SONU341	CMS	P1.0	Sonus	ASX Access Server	V06.01.00F004	SUNFIRE V120				
CW34	5TAZZ341	Policy Server	PCMM	Tazz Networks	TAZZ PCS	PCMM 1.2	SUN V60/V20z				
CW34	THOM341	EMTA	P1.0,D2.0,D1.1	Technicolor	DHG525	ST62.06.00	5.0				Technicolor formerly known as Thomson
CW34	5TELC341	Policy Server	PCMM	Telcordia	Policy Manager 1.0	PS-R1.0-200502091200	SUNW,Ultra-80				
CW34	TERA341	EMTA	P1.0,D2.0,D1.1	Terayon	TJ945	16.0.0.9	31.0				
CW33	AMBI331	Embedded PS	C1.1,D2.0,D1.1	Ambit	U10C019	5.66.1000	4.10				
CW33	LINK331	CM	D2.0,D1.1	Cisco-Linksys, LLC	BEFCMU10 ver. 5	2.0.3.5.6	2.0				
CW33	LINK332	EMTA	P1.0,D2.0,D1.1	Cisco-Linksys, LLC	CM2P2B	2.0.3.5.6	2.1				
CW33	LINK333	EMTA	P1.0,D2.0,D1.1	Cisco-Linksys, LLC	CG2P2WB	2.0.3.5.6	2.1				
CW33	SCIE331	EMTA	P1.0,D2.0,D1.1	Scientific Atlanta	DPX2203	v2.0.2r1151	2.1				
CW33	SCIE332	EMTA	P1.0,D2.0,D1.1	Scientific Atlanta	DPX2213	v2.0.2r1251	1.0				
CW33	THOM331	EMTA	P1.0,D2.0,D1.1	Technicolor	DHG525	ST62.05.00	5.0				Technicolor formerly known as Thomson
CW32	2ARRI321	CMTS+DSG	D2.0,D1.1	Arris	C4-CMTS-2100-1	CMTS_V04.02.00.10	2.0				
CW32	ARRI321	CM	D2.0,D1.1	Arris	TM402G	4.4.1	07				
CW32	1BIGB321	CMTS+DSG	D1.1	Bigband Networks	Cuda 12000 (C12-DM2x8-2.0)	R5.5.0	Rev 4				
CW32	LINK321	Embedded PS	C1.1,D2.0,D1.1	Cisco-Linksys, LLC	CG2P2WB	2.0.3.4.2	2.0				
CW32	2MOTO321	CMTS+DSG	D2.0,D1.1	Motorola	BSR 64000	4.1.0T08P10.KRAU	CHS-0009-01				
CW32	NTGR321	Embedded PS	C1.1,D2.0,D1.1	Netgear	CG814WG	3.4.2	1.02				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW32	SCIE321	DSG+ECM	DSG,D1.0	Scientific Atlanta	8300 DVLPR	2.23.7	1.0				Verified for Interoperability
CW32	THOM321	Embedded PS	C1.1,D2.0,D1.1	Technicolor	DCW725	ST5A.06.01	4.1				Technicolor formerly known as Thomson
CW32	TERA321	CM	D2.0,D1.1	Terayon	TJ716x	15.0.0.20	56.1				
CW32	TOLL321	CM	D1.1	Tollgrade	1.0.0	1.0.2	10.0				
CW32	ZOOM321	CM	D2.0,D1.1	Zoom	5241	5.35.33.5	100			CONE291	
CW32	ZYXE321	Embedded PS	C1.1,D2.0,D1.1	Zyxel	Prestige 971	V3.70.01	V4.1				
CW32	ZYXE322	Embedded PS	C1.1,D2.0,D1.1	Zyxel	Prestige 974	V3.70.01	V3.9				
CW31	AMCO311	CM	D1.1	AM Communications	9362	1.68	4.0				
CW31	1CISC311	CMTS+PC	P1.1,P1.0,D1.1	Cisco	uBR7246 VXR/MC28U	12.2(15)BC2p1	MC28U:Rev 6.5				
CW31	ELEC311	CM	D1.1	Electroline	DHT-PS-NA-01	2.14	02				
CW31	MOTO311	EMTA	P1.0,D2.0,D1.1	Motorola	SBV5220	SBV5220-2.10.0.0-SCM11-NOSH	1				
CW31	TOLL311	CM	D1.1	Tollgrade	1.0.0	1.0.2	1.0.0				* This product is certified only for the uses as defined in the executive summary of the certification application.
CW30	AMBI301	EMTA	P1.0,D2.0,D1.1	Ambit	U10C017	4.36.1007	2.22				
CW30	LINK301	EMTA	P1.0,D2.0,D1.1	Cisco-Linksys, LLC	CM2P2B	2.0.3.2.5	2.0				
CW30	LINK302	EMTA	P1.0,D2.0,D1.1	Cisco-Linksys, LLC	CG2P2WB	2.0.3.2.5	2.0				
CW30	ELEC302	CM	D1.1	Electroline	DHT-PS-NA-01	2.10	01				
CW30	2MOTO301	CMTS	D2.0,D1.1	Motorola	BSR 64000	4.1.0T04P15.KRAU	CHS-0009-01				
CW30	MOTO301	CM	D2.0,D1.1	Motorola	SBV5220	SBV5220-2.9.1.0-SCM08-NOSH	1				
CW30	SCIE301	EMTA	P1.0,D2.0,D1.1	Scientific Atlanta	DPX2203	v2.0.2r1143	2.1				
CW30	THOM302	Embedded PS	C1.1,D2.0,D1.1	Technicolor	DCW725	ST5A.02.01	4.0				Technicolor formerly known as Thomson
CW30	TERA301	CM	D2.0,D1.1	Terayon	TJ716x	14.0.1.4101	35.0				
CW29	1ADCO291	CMTS	D1.1	ADC	Cuda 12000 (C12-DM2X8-2.0)	R5.5.0	Rev 4				
CW29	AMBI291	CM	D2.0,D1.1	Ambit	U10C018	2.93.1003	1.20				
CW29	2ARRI291	CMTS	D2.0,D1.1	Arris	C4-CMTS-2100-1	CMTS_V04.00.00.104	2.0				
CW29	4AUDC291	MG	P1.0	AudioCodes	Mediant 5000	2.0.30_1.6	Rev. B				
CW29	LINK291	CM	D2.0,D1.1	Cisco-Linksys, LLC	BEFCMU10 ver. 4	2.0.3.1.1	2.0				
CW29	LINK292	Embedded PS	C1.1,D2.0,D1.1	Cisco-Linksys, LLC	WCG200 ver. 2	2.0.3.1.1	2.0				
CW29	LINK293	Embedded PS	C1.1,D2.0,D1.1	Cisco-Linksys, LLC	CGV2W	2.0.3.1.1	2.0				
CW29	CONE291	CM	D2.0,D1.1	Conexant	ACM951	5.35.33.5	100				
CW29	CONE292	CM	D2.0,D1.1	Conexant	XCM951	5.35.33.5	10				
CW29	4GENE291	MG	P1.0	Genband	G6	rel_1001_0_0_BP	1.0				Genband formerly known as General Bandwidth
CW29	1MOTO291	CMTS+PC	P1.1,P1.0,D1.1	Motorola	BSR 64000	3.1.0T00P57.05.KRBU	CHS-0009-01				
CW29	1MOTO292	CMTS	D1.1	Motorola	BSR 64000	3.1.0T00P57.05.KRBU	CHS-0009-01				
CW29	MOTO291	CM	D2.0,D1.1	Motorola	SB5120	SB5120-2.13.0.2-SCM05-NOSH	4				
CW29	MOTO292	EMTA	P1.0,D2.0,D1.1	Motorola	SBV5120	SBV5120-2.9.0.1-SCM16-NOSH	1				
CW29	SCIE291	CM	D2.0,D1.1	Scientific Atlanta	WebSTAR DPC2100	v2.0.2r1142	1.2				
CW29	SCIE292	CM	D2.0,D1.1	Scientific Atlanta	WebSTART DPC2100	v2.0.2r1242	2.0				
CW29	THOM291	CM	D2.0,D1.1	Technicolor	DCM425	ST52.01.02	4.0				Technicolor formerly known as Thomson
CW28	AMBI281	CM	D2.0,D1.1	Ambit	10018EU	2.93.1000	1.18				
CW28	AMBI282	Embedded PS	C1.0,D1.1	Ambit	60740EU	5.11.1111	4.7				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW28	2ARRI281	CMTS	D2.0,D1.1	Arris	710622	4.0.1.45	04				
CW28	ARRI281	EMTA	P1.0,D2.0,D1.1	Arris	TM402P	TS.04.01.01.013004C	04				
CW28	ASKE281	CM	D2.0,D1.1	Askey Computer Corp.	CME100	2.0.2.0.6	2.1				
CW28	CAST281	CM	D2.0,D1.1	Castlenet	DP1110XB2A	2.7.2.280	1.0				
CW28	CAST282	CM	D2.0,D1.1	Castlenet	DP1110XB2	2.5.2.117	1				
CW28	1CISC281	CMTS+PC	P1.1,P1.0,D1.1	Cisco	uBR7246 VXR/MC28U	12.2(15)BC2p	MC28U: Rev 6.5				
CW28	LINK281	Embedded PS	C1.1,D2.0,D1.1	Cisco-Linksys, LLC	WCG200	2.0.2.10.0	1.2b				
CW28	CONE281	CM	D2.0,D1.1	Conexant	ACM951	5.29.30.6.MOOB	100				
CW28	CONE282	CM	D2.0,D1.1	Conexant	XCM951	5.29.30.6.MIAMI	010				
CW28	DAEH281	CM	D2.0,D1.1	Daehanet. Inc.	LP3200	10.2.0	29.2			JHCO261	
CW28	DLIN281	CM	D2.0	Dlink	DCM-202	2.0.1	1A			HITR252	
CW28	ELEC281	CM	D1.1	Electroline	DHT-PS-NA-01	2.00	01				
CW28	3NORT281r1	MGC	P1.0	Genband	CS 2000 MGC	SN06.PSM	SN06.PHM				Genband formerly known as Nortel Networks
CW28	MOTO281	CM	D2.0,D1.1	Motorola	SBG940	SBG940-2.1.8.1-SCM00-NOSH	1				
CW28	MOTO282	Embedded PS	C1.0,D2.0,D1.1	Motorola	SBG940	SBG940-2.1.8.1-SCM00-NOSH	1				
CW28	MOTO283	CM	D2.0,D1.1	Motorola	SBV5120	SBV5120-2.8.0.4-SCM02-NOSH	1				
CW28	MOTO286	CM	D2.0,D1.1	Motorola	SBG900	2.1.8.2SCM01	3				
CW28	MOTO287	CM	D2.0,D1.1	Motorola	SB5101	SB5101-2.4.0.1-SCM00-NOSH	1				
CW28	NTGR281	Embedded PS	C1.1,D2.0,D1.1	Netgear	CG814WG	2.10.0R01	1.02				
CW28	COSH281	CM	D2.0,D1.1	Shenzhen Coship Electronics Co., Ltd	CCM2000A	12.0.2.13	35.0				
CW28	OSIEM281	CMS	P1.0	Siemens	Surpass hiQ 8000	06.02.01.US.09	Sun Microsystems Netra 1400T				
CW28	THOM281	CM	D2.0,D1.1	Technicolor	DCM325	ST32.0D.00	1.7				Technicolor formerly known as Thomson
CW28	THOM282	CM	D1.0	Technicolor	DCM325	ST31.08.01	1.7				Technicolor formerly known as Thomson
CW28	TOSH281	CM	D1.1	Toshiba	PCX1100/DAZ8	1.8.022	6.11				
CW28	TOSH282	CM	D1.1	Toshiba	PCX1100U/DAZ8 813	1.8.022	6.62				
CW27	AMBI272	Embedded PS	C1.0	Ambit	60740EUW	5.11.1111	4.7				
CW27	BEST271	CM	D1.1	BestData	CMX300v2	0.14457.2570	10			CAST261	
CW27	CABL271	CM	D2.0	Cablerex	CRM3800	7.0.2	6.0.1			XROS241	
CW27	0CISC271	CMS	P1.0	Cisco	BTS10200	RLS 4.1Q11	BTS10200				
CW27	1CISC271	CMTS	D1.1	Cisco	uBR7246VXR/M C28U	12.2(15)CXc1	MC28U: Rev. 6.2				
CW27	3CISC271	MGC	P1.0	Cisco	BTS10200	RLS 4.1Q11	BTS10200				
CW27	LINK271	CM	D2.0	Cisco-Linksys, LLC	BEFCMU10 ver. 3	2.0.2.0.1	1.0				
CW27	0CEDA271	CMS	P1.0	Genband	SAFARI	R3.0.9.3	1.2				Genband formerly known as Cedar Point
CW27	MOTO271	Embedded PS	C1.0	Motorola	SBG900	SBG900-2.1.6.2-SCM02-NOSH	2				
CW27	MOTO272	CM	D2.0	Motorola	SBG900	SBG900-2.1.6.0-SCM04-NOSH	2				
CW27	MOTO273	CM	D2.0	Motorola	SB5100	SB5100-2.3.1.6-SCM01-NOSH	3				
CW27	NTGR271	Embedded PS	C1.0	Netgear	CG814WG	2.92R01	1.02				
CW27	SCIE271	EMTA	P1.0	Scientific Atlanta	WebSTAR DPX2203	v2.0.1r1133	1.1				
CW27	SCIE272	Embedded PS	C1.0	Scientific Atlanta	WebSTAR DPR2320	v2.0.1r1133	1.1				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW27	SCIE273	CM	D2.0	Scientific Atlanta	WebSTAR DPC2100	v2.0.1r1133	1.1				
CW27	SCIE274	CM	D2.0	Scientific Atlanta	WebSTAR DPX2100	v2.0.1r1134	1.3				
CW27	THOM271	CM	D2.0	Technicolor	DCM315	ST32.0A.00	3.1				Technicolor formerly known as Thomson
CW27	OTELC271	CMS	P1.0	Telcordia	Telcordia Call Agnet	2.3.3	Sun Ultra 80				
CW27	TERA272	CM	D2.0	Terayon	TJ815g	4.21.5	41.0				
CW27	TOSH271	CM	D2.0	Toshiba	PCX2600/DAZ8823	3.0.14	19.0.1				
CW27	ZYXE271	CM	D2.0	Zyxel	Prestige 964 CM/Router WG	3.61	3.6				
CW26	1ADCO261	CMTS+PC	P1.0	ADC	Cuda 12000	R5.0.0	CMTS: Rev 4				
CW26	AMBI261	CM	D1.1	Ambit	60678EU	2.57.1002	1.12				
CW26	1ARRI261	CMTS	D1.1	Arris	CMTS 2000	3.2.1.100.001	02				
CW26	ASKE261	CM	D2.0	Askey Computer Corp.	CME100	2.0.2.0.1	2.1				
CW26	BELK261	CM	D1.1	Belkin	F5D5530-W	0.14457.2571	10				
CW26	CAST261	CM	D1.1	Castlenet	CXC150	0.14457.2570	10				
CW26	CAST262	CM	D1.1	Castlenet	CXC250	5.19.20.2.FORTMESH.2561	010				
CW26	CISC261	CM	D1.1	Cisco	Ubr925	12.2	3.i				
CW26	OCEDA261	CMS	P1.0	Genband	SAFARI	2.0.7.3	1.1				Genband formerly known as Cedar Point
CW26	0NORT261	CMS	P1.0	Genband	CS 2000	SN06.PSC	SN06.PHC				Genband formerly known as Nortel Networks
CW26	JHCO261	CM	D2.0	Joohong	SL2810	10.2.0	29.2				
CW26	MOTO261	CM	D2.0	Motorola	SB5100	SB5100-2.3.0.9-SCM01-NOSH	3				
CW26	MOTO262	CM	D2.0	Motorola	SBG900	SBG900-2.1.3.4-SCM09-NOSH	1				
CW26	MOTO263	CM	D1.1	Motorola	SBG1000	SBG1000-1.1.3.5-SCM00-NOSH	1				
CW26	MOTO264	CM	D1.1	Motorola	SB3100	SB3100-1.4.8.13-SCM01-NOSH	1				
CW26	NTGR261	Embedded PS	C1.0	Netgear	CG814WG	2.90R01	1.02				
CW26	4NUER261	MG	P1.0	Nuera Communications	BTX-8	2.0	2.0				
CW26	SMCN262	CM	D1.1	SMC	SMC8004CM	2.0.1	1A			HITR251	
CW26	SCIE261	CM	D1.0	Scientific Atlanta	WebSTAR DPX2100	v.1.0.1r1131-0424	1.11				
CW26	SCIE263	Embedded PS	C1.0	Scientific Atlanta	WebSTAR DPR2320	v2.0.1r1132	1.1				
CW26	SCIE264	EMTA	P1.0	Scientific Atlanta	WebSTAR DPX2203	v2.0.1r1132	1.1				
CW26	SCIE265	CM	D2.0	Scientific Atlanta	WebSTAR DPC2100	v2.0.1r1132	1.0				
CW26	THOM261	CM	D1.0	Technicolor	DCM315/DCM315R	ST31.07.00	1.3				Technicolor formerly known as Thomson
CW26	THOM262	CM	D1.0	Technicolor	DCW625/DCW625R	ST41.03.00	1.1				Technicolor formerly known as Thomson
CW26	THOM263	CM	D2.0	Technicolor	DCM316/DCM316R	ST36.10	50.1				Technicolor formerly known as Thomson
CW26	THOM264	CM	D1.0	Technicolor	DCM315, DCM315R (retail)	ST31.08.00	1.5				Technicolor formerly known as Thomson
CW26	THOM265	CM	D1.1	Technicolor	DCW615 (DCW615R)	ST49.04.00	1.4				Technicolor formerly known as Thomson
CW26	TERA262	EMTA	D2.0	Terayon	TA-102	6.0.1v	9.3				
CW26	TERA263	CM	D2.0	Terayon	TJ715X	6.22	10.0				
CW26	TEXA261	CM	D2.0	Texas Instruments	TNETC421A	10.2.4	51.2				
CW26	LINK261	CM	D1.1	The Linksys Group, Inc.	BEFCMU10 ver 3	1.1.1.0.1	1.0				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW26	LINK263	CM	D1.1	The Linksys Group, Inc.	WCG200	1.1.3.0.1	1.2b				
CW26	LINK264	CM	D1.1	The Linksys Group, Inc.	WCG200	1.1.3.0.1	1.2b				
CW26	TOSH262	EMTA	P1.0	Toshiba	PCX3000	7.2.3	13.0.0				
CW26	TOSH263	CM	D1.1	Toshiba	PCX2200/DAZ8817	1.8.017	7.4				
CW26	ZYXE261	CM	D2.0	Zyxel	Prestige 964	3.60	3.6				
CW25	AMBI251	CM	D2.0	Ambit	60678EU	2.57.2007	1.12				
CW25	AMBI253	Embedded PS	C1.0	Ambit	60740EUW	5.11.1001	4.6				
CW25	1ARRI251	CMTS+PC	P1.0	Arris	C4-CMTS-2100-1	CMTS_V03.01.00.20	1.3				
CW25	ARRI251	EMTA	P1.0	Arris	TTM202P	TM.03.02.020703C	05				
CW25	ARRI252	CM	D1.1	Arris	CM450A	CM.04.02.011703C	01				
CW25	ARRI253	CM	D2.0	Arris	CM450A	CM.04.02.011703C	01				
CW25	CAST253	CM	D2.0	Castlenet	CXC250	5.12.12.1	010				
CW25	0CISC251	CMS	P1.0	Cisco	BTS10200	R4.0	R4.0				
CW25	1CISC251	CMTS+PC	P1.0	Cisco	uBR10012	12.2(11)BC2p	Rev 4.0 MC28 Rev A0				
CW25	1CISC252	CMTS	D1.1	Cisco	uBR7114	12.2(11)BC3c	Rev 1.3				
CW25	1CISC253	CMTS+PC	P1.0	Cisco	uBR7246vrx	12.2(11)BC2p	rev B0, MC16S rev 1.0, NPE400: :RevA0, HW 1.03				
CW25	CMTO251	CM	D2.0	Com21	DP1110XB2	2.5.2.111	1				
CW25	CORR251	CM	D1.1	Correlant	EC330A	9.2.9	17.0				
CW25	DXAN251	CM	D1.0	DX Antennae	CDM-130/DAZ8821	1.0.6	9.1.1			TOSH221	
CW25	DLIN251	CM	D1.1	Dlink	DCM-201	1.1.0	4A			HITR231	
CW25	HITR251	CM	D1.1	Hitron	BRG-3520T	2.0.1	1A				
CW25	HITR252	CM	D2.0	Hitron	BRG-3520T	2.0.1	1A				
CW25	KIPO251	CM	D1.1	Kinpo	CMD1001	5.26	7.0				
CW25	1MOTO251	CMTS+PC	P1.0	Motorola	BSR 64000	1.3.0T04P21.KRAU	PCA-0100				
CW25	MOTO252	CM	D1.1	Motorola	SB5120	SB5120-2.9.2.9-SCM-03-NOSH	1				
CW25	MOTO253	CM	D2.0	Motorola	SB5120	SB5120-2.9.2.9-SCM-03-NOSH	1				
CW25	MOTO255	EMTA	P1.0	Motorola	SBV4200	SBV4200-07.2.04-SCM00-NOSH	1				
CW25	MOTO256	CM	D2.0	Motorola	SB5120	SB5120-2.9.3.9-SCM-03-NOSH	2				
CW25	MOTO259	CM	D1.1	Motorola	SB3100	SB3100-1.4.8.13-SCM00-NOSH	1				
CW25	NTGR251	CM	D1.1	Netgear	CG814Mv2	2.0.0	1A				
CW25	SMCN253	CM	D1.1	SMC	SMC8013WG	2.0.0	1A				
CW25	SCIE251	CM	D2.0	Scientific Atlanta	WebSTAR DPX2100	2.0.1r1.1.3.1	1.1				
CW25	SCIE252	CM	D1.1	Scientific Atlanta	WebSTAR DPX100	1.1.2r1.1.3.1	2.1				
CW25	0SYND251	CMS	P1.0	Syndeo	SYION426	2.2.6.8	SUNBLADE1000				
CW25	THOM251	CM	D1.0	Technicolor	DCM315, DCM315R	ST31.04.00	1.2				Technicolor formerly known as Thomson
CW25	THOM252	CM	D2.0	Technicolor	DCM315, DCM315R	ST32.06.00	1.2				Technicolor formerly known as Thomson
CW25	THOM253	CM	D1.1	Technicolor	DCW615,DCW615R	2.81R01	1.40				Technicolor formerly known as Thomson
CW25	THOM254	Embedded PS	C1.0	Technicolor	DCW615, DCW615R	2.82R03	1.40				Technicolor formerly known as Thomson
CW25	2TERA251	CMTS+PC	P1.0	Terayon	BW-3500	2.0.0.1.21	2.0				
CW25	TERA251	CM	D1.1	Terayon	TA-102	2215	8.15				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW25	TERA252	CM	D1.1	Terayon	TJ715	5.26	9.0				
CW25	TERA253	CM	D2.0	Terayon	TJ715	6.20	9.0				
CW25	TERA254	CM	D2.0	Terayon	TJ715	6.20	7.0				
CW25	TERA255	CM	D1.1	Terayon	TJ715X	5.25	7.0				
CW25	LINK251	CM	D1.1	The Linksys Group, Inc.	BEFCMU10	1.1.5	3.0				
CW25	LINK255	CM	D2.0	The Linksys Group, Inc.	WCG200	2.0.1.0.1	1.0b				
CW25	LINK256	Embedded PS	C1.0	The Linksys Group, Inc.	WCG200	2.0.1.0.2	1.0b				
CW25	LINK257	CM	D1.1	The Linksys Group, Inc.	WCG200	2.0.1.0.1	1.0b				
CW25	TOSH251	CM	D1.0	Toshiba	PCX2600/DAZ8823	1.0.13	19.0.0				
CW25	TOSH252	CM	D2.0	Toshiba	PCX2600/DAZ8823	3.0.13	19.0.0				
CW25	TOSH253	CM	D1.0	Toshiba	PCX4500/DAZ8841	1.0.0	17.0.0				
CW24	AMBI241	CM	D1.1	Ambit	60194E	2.23.1099	1.6				
CW24	AMBI242	CM	D1.1	Ambit	60678EU	2.57.1001	1.12				
CW24	1ARRI242	CMTS	D1.1	Arris	ARCD00048	4.2.8	01				
CW24	ARRI241	EMTA	P1.0	Arris	TM02DB102	3.5.1	04				
CW24	ARRI241	CM	D1.1	Arris	TM02DB102	3.5.1	04				
CW24	ARRI242	CM	D1.1	Arris	TC00DA103	4.2.0	01				
CW24	ARRI243	CM	D1.1	Arris	TC00DA1430	1.1.0	02				
CW24	ASKE241	CM	D1.1	Askey Computer Corp.	CME100	1.1.1 r1	1.0				
CW24	BROA241	CM	D1.1	Broadxent	8601	1.1.5 r1	5.2				
CW24	1CISC241	CMTS+PC	P1.0	Cisco	UBR7246 VXR	12.2 (11)BC1c	Rev B0 MC16S rev 1.0, NPE400				
CW24	1CISC241	CMTS	D1.1	Cisco	UBR10012	12.2(11)BC2c1	Rev 3.0 MC5x20S rev. 5.0				
CW24	1CISC242	CMTS+PC	D1.1	Cisco	uBR7200 VXR	12.2(11)BC1c	rev B0, MC16S rev 1.0, NPE400: Rev A0, HW 1.03				
CW24	CMT0241	CM	D1.1	Com21	DP1110XB2	2.5.2.110	1				
CW24	KIPO241	CM	D1.1	Kinpo	CMD1001	5.25	7.0				
CW24	MOTO242	CM	D1.1	Motorola	SB5100	SB5100-1.1.1.1-SCM01-NOSH	1				
CW24	MOTO243	CM	D2.0	Motorola	SB5100	SB5100-1.1.1.1-SCM01-NOSH	1				
CW24	NTGR241	Embedded PS	C1.0	Netgear	CG314WH	2.64	1.30				
CW24	PION241	CM	D1.1	Pioneer	BT-M850W	1.1.1.r1	1.0				
CW24	1SCIE231	CMTS	D1.1	Scientific Atlanta	Prisma G1	2.1.1.16B	M2.0-G1			1Jnpr231	
CW24	SCIE241	CM	D2.0	Scientific Atlanta	WebSTAR DPX2100	2.0.1 r4	1.1				
CW24	SCIE242	EMTA	P1.0,D1.1	Scientific Atlanta	WebSTAR DPX203	1.0.4 r4	5.0				
CW24	SCIE243	CM	D1.1	Scientific Atlanta	WebSTAR DPR362	1.1.1r3	1.0				
CW24	THOM241	CM	D1.0	Technicolor	DCM315	ST31.01.00	1.1				Technicolor formerly known as Thomson
CW24	THOM242	CM	D1.0	Technicolor	DCM305 and DCM305R (retail)	ST23.1B.41	028				Technicolor formerly known as Thomson
CW24	THOM244	CM	D1.1	Technicolor	DCM318/318R	5.25	8.0				Technicolor formerly known as Thomson
CW24	2TERA241	CMTS	D2.0	Terayon	BW3500	2.0.0.0.21	2.0				
CW24	2TERA241	CMTS+PC	P1.0	Terayon	BW3500	2.0.0.0.21	2.0				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW24	TERA241	EMTA	D1.1	Terayon	TA-102	221	8.15				
CW24	TERA242	CM	D1.1	Terayon	TJ715	5.25	7.0				
CW24	TERA243	CM	D2.0	Terayon	TJ715	6.19	3.0				
CW24	TEXA241	CM	D1.1	Texas Instruments	CX3000	8.2.2	200.2				
CW24	TEXA242	CM	D2.0	Texas Instruments	TNETC406	27.8.2	13.1				
CW24	LINK241	Embedded PS	C1.0	The Linksys Group, Inc.	BEFCMUH4	2.64	1.30				
CW24	TOSH241	EMTA	P1.0,D1.1	Toshiba	PCX3000/DAZ8831	6.2.3	13.0.0				
CW24	TOSH243	CM	D1.0	Toshiba	PCX2200A/DAZ8818	1.7.022	7.6				
CW24	TOSH245	CM	D1.1	Toshiba	PCX201/DAZ7781	1.0.0	17.0.0				
CW24	XROS241	CM	D2.0	Xrosstech	XCM-3800	7.0.2	6.0.1				
CW23	ARRI231	CM	D1.1	Arris	CM00DA103	3.3.0	01				
CW23	ASKE231	CM	D1.1	Askey Computer Corp.	CME075	1.1.4 r1	5.4				
CW23	BELK231	CM	D1.1	Belkin	F5D5530-W	0.13645-2310	10				
CW23	CAST231	CM	D1.1	Castlenet	CXC150	0.13645.2310	10				
CW23	CMTO231	CM	D1.1	Com21	DP1110XB	2.3.2.109	3				
CW23	EFFI231	CM	D1.0	Efficient Networks	SpeedStream 6101	2.22.2	1.8				
CW23	FNTS231	CM	D1.1	Fujitsu	FSC102	1.1.2 r1	5.1			ASKE211	
CW23	HITR231	CM	D1.1	Hitron	BRG-3520	1.1.0	4A				
CW23	INTE231	CM	D1.1	Intel	5200	14.5.4	9				
CW23	1JNPR231	CMTS	D1.1	Juniper Networks	Juniper G1	2.1.1.16b	M2.0-G1				
CW23	1MOTO231	CMTS	D1.1	Motorola	BSR 64000	1.3.0T03P08A.KRBU	PCA-0100				
CW23	MOTO231	CM	D1.0	Motorola	SBG1000	SBG1000-0.1.1.1-SCM03-NOSH	1				
CW23	MOTO232	CM	D1.0	Motorola	SB4300	2.7.1b	1				
CW23	NTGR231	CM	D1.0	Netgear	CM212	1.01	3A			HITR201	
CW23	NTGR232	CM	D1.0	Netgear	CG814W	2.63	1.10				
CW23	SMCN231	CM	D1.0	SMC	SMC8012WG	2.63	1.00				
CW23	SCIE231	CM	D1.0	Scientific Atlanta	WEBSTAR DPX100	1.0.5 r1.1.3	2.1				
CW23	SCIE232	CM	D1.0	Scientific Atlanta	Webstar DPX 2100	2.0.1r	1.0				
CW23	THOM231	CM	D1.1	Technicolor	DCM305/DCM305R	ST24.13.40	028				Technicolor formerly known as Thomson
CW23	THOM232	CM	D1.0	Technicolor	DCW232	2.63	1.30				Technicolor formerly known as Thomson
CW23	1TERA231	CMTS	D1.1	Terayon	BW3500	1.3.21.2	2.0				
CW23	LINK231	CM	D1.1	The Linksys Group, Inc.	BEFCMUH4	2.63	1.30				
CW23	LINK233	CM	D1.1	The Linksys Group, Inc.	BEFCMU10 Ver 2	1.1.4	4.0				
CW23	TOSH231	CM	D1.0	Toshiba	PCX2500/DAZ8821	1.0.11	9.2.3				
CW23	TOSH232	CM	D1.0	Toshiba	PCX5000/DAZ8850	1.7.021SV	7.31				
CW23	TOSH233	CM	D1.0	Toshiba	PCX2200/DAZ8817	1.7.021	7.4				
CW22	3COM221	CM	D1.1	3Com	3CR29223	02.06	2.00				
CW22	1ADCO221	CMTS	D1.1	ADC	Cuda 12000 (C12-DM1x6SPM-SF)	R3.1.23	CMTS: Rev A5				
CW22	1ADCO222	CMTS	D1.1	ADC	Cuda 12000 (C12-DM1 x4SPM-SF)	R3.1.23	CMTS Rev. 23				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW22	1ARRI221	CMTS	D1.1	Arris	C4-CMTS-2100-1	v02.00.02.10	1.0				
CW22	1ARRI222	CMTS	D1.1	Arris	ARCD00048	4.2.6	01				
CW22	ASUS222	CM	D1.0	Asustek	ACM6045EB	1.9	1.4				
CW22	BROA221	CM	D1.1	Broadxent	8601	1.1.2 r1	5.1			ASKE211	
CW22	1CISC221	CMTS	D1.1	Cisco	UBR7200VXR/M C28C	12.2(7)BC1c	NPE-400: Rev A0 HW 1.03, MC28C: Rev B0 HW 2.03				
CW22	CMTO221	CM	D1.0	Com21	DP 1110XB	2.3.1.108	3				
CW22	CMTO222	CM	D1.1	Com21	DP 1110XB	2.3.2.108	03				
CW22	CORR221	CM	D1.1	Correlant	EC270	1.8.10	7.41				
CW22	FNTS221	CM	D1.1	Fujitsu	FSC102	1.1.2 r1	5.1			ASKE211	
CW22	JHCO222	CM	D1.1	Joohong	SL-2800	Ver6.1.0	Ver2.1				
CW22	1JNPR221	CMTS	D1.1	Juniper Networks	Juniper G10	2.1.0.18	2.0				
CW22	1MOTO221	CMTS	D1.1	Motorola	BSR 64000	1.2.47.KRC	PCA-0057-02				
CW22	1MOTO222	CMTS	D1.1	Motorola	BSR 1000	01.01.15.PRR	PCA-0027-030				
CW22	MOTO221	CM	D1.0	Motorola	SB4220	SB4220-0.6.3.0-SCM-01-NOSH	1				
CW22	MOTO222	CM	D1.1	Motorola	SB4220	SB4220-1.6.3.0-SCM-01-NOSH	1				
CW22	MOTO223	CM	D1.1	Motorola	SB4100	1.4.8.5	0				
CW22	MOTO224	CM	D1.1	Motorola	SB4200	SB4200-1.4.8.4-SCM01-NOSH	1				
CW22	PION221	CM	D1.0	Pioneer	BT-M800W	1.0.7 r1	3.0				
CW22	1SCIE221	CMTS	D1.1	Scientific Atlanta	Prisma G10	2.1.0.18	2.0			1JNPR221	
CW22	SCIE221	CM	D1.0	Scientific Atlanta	WebStar DPX100	1.0.5 r1.1	1.0				
CW22	SCIE222	CM	D1.0	Scientific Atlanta	WebStar DPX100	1.0.5 r1.1	2.1				
CW22	SCIE223	CM	D1.0	Scientific Atlanta	WebStar DPX100	1.0.5 r1.1	2.2				
CW22	THOM221	CM	D1.0	Technicolor	DCM305/305R	ST22.05.01	028				Technicolor formerly known as Thomson
CW22	THOM222	CM	D1.0	Technicolor	DCM305/305R	ST23.10.00	028				Technicolor formerly known as Thomson
CW22	TEXA221	CM	D1.1	Texas Instruments	TNETC405T	6.3.0	9.1				
CW22	LINK222	CM	D1.0	The Linksys Group, Inc.	BEFCMUH41	1.0.0	0A				
CW22	LINK223	CM	D1.0	The Linksys Group, Inc.	BEFCMUH4	2.62	1.10				
CW22	TOSH221	CM	D1.0	Toshiba	PCX2500/DAZ88 21	1.0.6	9.1.1				
CW22	TOSH222	CM	D1.1	Toshiba	PCX2500/DAZ88 21	2.0.7	9.2.2				
CW22	TOSH224	CM	D1.0	Toshiba	PCX2200	1.7.017	7.3				
CW21	1ADCO211	CMTS	D1.1	ADC	Cuda 12000	R3.1.91	20				
CW21	AAST211	CM	D1.0	Aastra	HM300c	71-0001-10	ROA 219 767/1 R1A				
CW21	1ARRI212	CMTS	D1.1	Arris	C4-CMTS2100	V01.01.00.12	1.0				
CW21	ARRI211	CM	D1.1	Arris	A2TM02NA	2.1.0	04				
CW21	ASKE211	CM	D1.1	Askey Computer Corp.	CME075	1.1.2 r1	5.1				
CW21	ASUS211	CM	D1.0	Asustek	ACM6045EB	1.80	1.00				
CW21	BEST211	CM	D1.0	BestData	CMX300	0.5096.360	04			CAST191	
CW21	1CISC211	CMTS	D1.1	Cisco	UBR10012	12.2(4)8Cc	Rev 4.0 MC28 RevA0				
CW21	CONE211	CM	D1.1	Conexant	CX9421CM	4.12734	24943.15.0				
CW21	CRSM211	CM	D1.0	Coresma	CM6011	0.5096.360	04			CAST191	
CW21	DXAN211	CM	D1.0	DX Antennae	CDM-120/DAZ8820	1.1R.005	3.2.1			TOSH182	

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW21	MOTO213	CM	D1.0	Motorola	SB4100	0.4.4.0p	Rev. 0				
CW21	MOTO214	CM	D1.0	Motorola	SB4200	0.4.4.0p	Rev. 1				
CW21	QUAN211	CM	D1.1	Quanta Network	QCM200	2.4.1	3.2				
CW21	1RSTN211	CMTS	D1.1	RiverStone	RS 8600	8.2.1.1	Backplane Rev A				
CW21	ACTN211	CM	D1.1	SMC	CM3503B-CSMC8011CM-B	2.3.1	3.0				
CW21	SAME211	CM	D1.1	Samsung Electronics	SCM-140U	2.1.0	14.00				
CW21	SCIE211	CM	D1.1	Scientific Atlanta	WebSTAR DPX100	1.1.2 r1	2.1				
CW21	SCIE212	CM	D1.1	Scientific Atlanta	WebSTAR DPX213	1.1.2 r1	1				
CW21	THOM211	CM	D1.1	Technicolor	DCM245/DCM245R	ST.1C.0D.00	026				Technicolor formerly known as Thomson
CW21	THOM212	CM	D1.0	Technicolor	RCA DCM305	ST22.04.00	028				Technicolor formerly known as Thomson
CW21	TELL211	CM	D1.1	Tellabs	CVM315A	2.5.0	RevA				
CW21	0TERA212	CMTS	D1.0	Terayon	B2800	6.1.2.C.1	300-005-03-0B			RiverStone	
CW21	TERA211	CM	D1.1	Terayon	ECM615	4.34	1.3				
CW21	TERA212	CM	D1.1	Terayon	ECM715	5.08	3.0				
CW21	LINK211	CM	D1.0	The Linksys Group, Inc.	BEFMCU10 ver.2	1.0.6	4.0				
CW21	LINK212	CM	D1.0	The Linksys Group, Inc.	BEFMCU10	1.0.4 Rel 2	3.0				
CW21	XROS211	CM	D1.1	Xrosstech	XCM-2300	V5.0.2	V5.1.2				
CW20	3COM201	CM	D1.0	3Com	3CR29223	01.22	2.00				
CW20	AMBI201	CM	D1.1	Ambit	60194E	2.25.988	1.8				
CW20	AMBI202	CM	D1.0	Ambit	60237EUW	5.1.309	4.2				
CW20	ARRI201	CM	D1.1	Arris	A2TM01NA	1.1.0	02				
CW20	0CISC201	CMTS	D1.0	Cisco	UBR10012	12.2(2)XF1	rev 3.0 MC28 rev A0				
CW20	1CISC201	CMTS	D1.1	Cisco	UBR7200 VXR/MC16S	12.1(7)CX2	rev B0 MC16S rev 1.0				
CW20	CISC201	CM	D1.0	Cisco	UBR925	Ver 12.2	3.i				
CW20	DLIN201	CM	D1.0	Dlink	DCM-200	4.4382.1	3.2				
CW20	ERIC201	CM	D1.1	Ericsson	HM206C	CXC 112 22391/1 R1B	ROA 117 8439/1 R2A 3A				
CW20	HITR201	CM	D1.0	Hitron	BRG-3520	1.0.1	3A				
CW20	MOTO201	CM	D1.0	Motorola	SB4100	0.4.3.3p	Rev. 0				
CW20	MOTO202	CM	D1.0	Motorola	SB4200	0.4.3.3p	Rev. 1				
CW20	0PBCO201	CMTS	D1.0	Pacific Broadband	Kodiak G10	2.0.0.16	2.0.0 (M2.0/A1.2/D2.0)				
CW20	PANA201	CM	D1.0	Panasonic	TZ-CM200	1.7.14	2.1				
CW20	OSCIA201	CMTS	D1.0	Scientific Atlanta	Prisma G10	2.0.0	2.0.0			1JNPR211	
CW20	SCIE201	CM	D1.0	Scientific Atlanta	WebSTAR DPX100	1.0.5 r1	1.0				
CW20	SCIE202	CM	D1.1	Scientific Atlanta	WebSTAR DPX100	1.1.1 r1	2.0				
CW20	THOM201	CM	D1.0	Technicolor	RCA DCM245	ST13.05.00	26				Technicolor formerly known as Thomson
CW20	TELL201	CM	D1.1	Tellabs	CVM410A	V3.20	V1.A				
CW20	TEXA201	CM	D1.1	Texas Instruments	TNETC405T	4.0.9	9.0				
CW20	TOSH201	CM	D1.0	Toshiba	PCX2500 / DAZ8821	1.0.2	9.1.0				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW20	TOSH202	CM	D1.1	Toshiba	PCX2500 / DAZ8821	2.0.2	9.1.0				
CW20	TOSH203	CM	D1.1	Toshiba	PCX3000 / DAZ8831	2.2.2	13.0.0				
CW20	TOSH204	CM	D1.0	Toshiba	PCX2200 / DAZ8817	1.7.014	7.1				
CW19	ACTN191	CM	D1.0	Accton	SMC8002CM	4.5096	9414.18.0				
CW19	AMBI191	CM	D1.0	Ambit	60194E	2.22.2	1.8				
CW19	1ARRI191	CMTS	D1.1	Arris	Cornerstone CMTS 1500	4.2.0	01				
CW19	ASKE191	CM	D1.0	Askey Computer Corp.	CMH033	1.0.4 Release 2	3.0			SCIE192	
CW19	ASKE192	CM	D1.0	Askey Computer Corp.	CME063	1.0.4 Release 2	4.0			SCIE191	
CW19	ASUS191	CM	D1.0	Asustek	ACM6050EB	1.60	1.30				
CW19	1CADA191	CMTS	D1.1	Cadant	C4-CMTS-2100	v00.80.17	1.0				
CW19	CAST191	CM	D1.0	Castlenet	CXC110	0.5096.360	04				
CW19	CORR191	CM	D1.0	Correlant	EC280T	1.7.11	7.11				
CW19	ERIC191	CM	D1.0	Ericsson	HM200c	CXC 112 2096/1 R5B	ROA 117 8439/1 R2A				
CW19	ERIC192	CM	D1.0	Ericsson	HM204c	CXC 112 2096/1 R5B	ROA 117 8439/1 R2A				
CW19	ERIC193	CM	D1.0	Ericsson	HM200c	R3G	R2B				
CW19	HAUP191	CM	D1.0	Hauppauge Computer	BRG-3510	1.0.9M1.2	A0			HITR181	
CW19	HIGH191	CM	D1.0	HighSpeed Surfing	SM200	0.5096.360	02				
CW19	LGIN191	CM	D1.0	LG Innotek	LCM100	4.5096	03				
CW19	LGIN192	CM	D1.0	LG Innotek	LCM5000	1.0.9M1.2	A0			HITR181	
CW19	MOTO191	CM	D1.0	Motorola	SB4000	4.2.12p	Rev. 1				
CW19	MOTO192	CM	D1.0	Motorola	SB4100	4.0.12p	Rev. 0				
CW19	MOTO193	CM	D1.0	Motorola	SB4101	4.0.12p	Rev. 4				
CW19	PANA191	CM	D1.0	Panasonic	TZ-CM200	1.7.11	2.1			Correlant EC280T	
CW19	SMCN191	CM	D1.0	SMC	SMC 8002 CM	2.8.3	1.6			AMBI181	
CW19	SAME191	CM	D1.0	Samsung Electronics	SCM-120U	1.1.1	12.20				
CW19	SCIE191	CM	D1.0	Scientific Atlanta	WebSTAR DPX110	1.0.4 Release 2	4.0				
CW19	SCIE192	CM	D1.0	Scientific Atlanta	WebSTAR DPX110	1.0.4 Release 2	3.0				
CW19	THOM191	CM	D1.0	Technicolor	DCM245 / DCM245R	ST12.07.01	26				Technicolor formerly known as Thomson
CW19	TERA191	CM	D1.0	Terayon	ECM610	3.47	1.2				
CW19	TERA192	CM	D1.0	Terayon	ECM615	3.52	1.2				
CW19	TEXA191	CM	D1.1	Texas Instruments	TNETC405	2.0.1	2.0.0				
CW19	LINK191	CM	D1.0	The Linksys Group, Inc.	BEFCMU10	1.0.3 Release 4	3.0			NORT171	
CW19	TOSH192	CM	D1.0	Toshiba	PCX1500/DAZ8816	1.7.011	7.1				
CW19	TOSH193	CM	D1.1	Toshiba	PCX2500/DAZ8821	2.0.1	9.00				
CW19	TOSH194	CM	D1.0	Toshiba	PCX1200/DAZ8815	1.7.011	7.0				
CW19	TRIG191	CM	D1.0	Tri-Gem Computer	Dream Port-1200	1.0.9M1.2	A0			HITR181	
CW19	TURB191	CM	D1.0	Turbocomm	EC200T	1.7.11	7.0				
CW19	ZOOM191	CM	D1.0	Zoom	Zoom Cable Modem 5041	4.100	140				
CW18	3COM181	CM	D1.0	3Com	3CR29250	2.10.5	1.6			Ambit	
CW18	3COM183	CM	D1.0	3Com	3CR29250	2.16.1	1.6			Ambit	

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW18	AMBI181	CM	D1.0	Ambit	60194E	2.8.3	1.6				
CW18	CAST181	CM	D1.0	Castlenet	CXC-110-DualLink	0.4590.230	04				
CW18	DLIN181	CM	D1.0	Dlink	DCM-200	4.4382	3.2			POWE171	
CW18	ERIC181	CM	D1.0	Ericsson	HM200c	CXC112 2096/1 R5A	ROA117 8439/1 R2A				
CW18	ERIC182	CM	D1.0	Ericsson	HM204C	CXC112 2096/1 R5A	ROA117 8439/1 R2A				
CW18	ERIC183	CM	D1.0	Ericsson	HM200c	R3D	R2B				
CW18	HIGH181	CM	D1.0	HighSpeed Surfing	SM100	0.4381.108	04			CAST172	
CW18	HITR181	CM	D1.0	Hitron	BRG-3510	1.0.9M1.2	A0				
CW18	HITR182	CM	D1.0	Hitron	BRG-3511	1.0.9W1.3	A0				
CW18	INF1181	CM	D1.0	Infinite	ICM1150T	VCMxm v1.8	ICM1150T Rev D				
CW18	NETS181	CM	D1.0	Net & Sys	MNG2000	2.1.0	4.0				
CW18	OPBCO181	CMTS	D1.0	Pacific Broadband	Kodiak F10	1.1.0.17	M1.1 / A1.7 / D1.1				
CW18	SAME181	CM	D1.0	Samsung Electronics	SCM-120U	1.0.0	12.20				
CW18	THOM181	CM	D1.0	Technicolor	DCM245/245R	ST12.07	26				Technicolor formerly known as Thomson
CW18	LINK181	CM	D1.0	The Linksys Group, Inc.	BEUCM11	0.4381.108	04			CAST172	
CW18	TOSH181	CM	D1.0	Toshiba	PCX 2000/DAZ8820	1.1R.006	3.3.2				
CW18	TOSH182	CM	D1.0	Toshiba	PCX 2000/DAZ8820	1.1R.005	3.2.1				
CW18	USRO181	CM	D1.0	US Robotics	USR6000	2.13.2	1.6			Ambit	
CW18	ZOOM181	CM	D1.0	Zoom	5001	1.86	0295-014 (MIB:295014)				
CW17	3COM172	CM	D1.0	3Com	3CR29223	01.15	2.0				
CW17	3COM173	CM	D1.0	3Com	3CR29241	01.03	2.0				
CW17	ACCT171	CM	D1.0	Accton	SMC 8001	2.1.0	2/1				
CW17	0ARRI171	CMTS	D1.0	Arris	Cornerstone CMTS-1500	4.0	00				
CW17	ASKE171	CM	D1.0	Askey Computer Corp.	CME063	1.0.3R4	3.0				
CW17	CAST171	CM	D1.0	Castlenet	CXC110-iCabler	0.4381.108	04				
CW17	CAST172	CM	D1.0	Castlenet	CXC110-CTI	0.4381.108	04				
CW17	0CISC172	CMTS	D1.0	Cisco	UBR 7100	ubr7100-k1p-mz.121-4.4.EC	Line card rev 3 upconv.rev7				
CW17	CISC171	CM	D1.0	Cisco	CVA 122	cva120-k1v4y5.mz.TLN	3.t				
CW17	DAKO171	CM	D1.0	Dakos	CableXpert CMZ1100	4.0.43.81	1.0				
CW17	ELSA171	CM	D1.0	Elsa	MicroLink Cable	1.0.8	A3			GVC	
CW17	ERIC171	CM	D1.0	Ericsson	HM200c R1A (ZAT 510 102/14)	R3D	R1A				
CW17	ERIC172	CM	D1.0	Ericsson	HM204c R1A (ZAT 510 112/14)	R4A	R1A				
CW17	GTSC171	CM	D1.0	Global Teleman	MediaLynx CM-2000	K	MediaLynx CM-2000 Rev. 0.5				
CW17	HIGH171	CM	D1.0	HighSpeed Surfing	SM110	0.4381.108	04			CAST172	
CW17	MATS171	CM	D1.0	Matsushita	TZ-CM100	1.1	1.1				
CW17	MOTO171	CM	D1.0	Motorola	SB3100	3.2.12p	Rev. 1				
CW17	MOTO172	CM	D1.0	Motorola	SB4100 Rev 0	4.2.1p	Rev. 1				
CW17	MOTO173	CM	D1.0	Motorola	SB4100 Rev 0	4.0.9p	Rev. 0				
CW17	MOTO174	CM	D1.0	Motorola	SB4100 Rev 1	4.0.9p	Rev. 1				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW17	NORT171	CM	D1.0	Nortel Networks	CM115U	1.0.3R4	3.0			ASKE171	
CW17	POWE171	CM	D1.0	Powercom	PCR-2600U	4.4382	V3.2				
CW17	ORSTN171	CMTS	D1.0	RiverStone	RS 8000	6.1.2.C.1			Backplane: 300-001-05-0A CMTS module: 02		
CW17	SAMA171	CM	D1.0	Samsung America	SCM-130U	V2.1.0	13/10				
CW17	SAMS171	CM	D1.0	Samsung Electronics	SCM-120R	4.4381	12.00				
CW17	SCIE171	CM	D1.0	Scientific Atlanta	Webstar DPX-110	1.0.3R4	3.0			ASKE171	
CW17	0TELL171	CMTS	D1.0	Tellabs	Cablespace 2700	6.1.2.C.1			Backplane: 300-005-06-0A CMTS module: 02		
CW17	0TERA171	CMTS	D1.0	Terayon	BE 2000/BE-CMTS41	6.1.2.C.1			Backplane: 300-001-05-0A CMTS module: 02		
CW17	TERA171	CM	D1.0	Terayon	ECM210	1.7.8	6.62			Correlant	
CW17	TEXA171	CM	D1.0	Texas Instruments	TNETC400G	.217	3.2				
CW17	LINK171	CM	D1.0	The Linksys Group, Inc.	BEUCM11	0.4381-108	04			CAST172	
CW16	AMBI161	CM	D1.0	Ambit	60218.P	v2.2 patch:9	v3.1				
CW16	0CISC161	CMTS	D1.0	Cisco	uBR7200/MC28C	12.1(3a)EC	A0				
CW16	1CISC161	CMTS	D1.1	Cisco	uBR7200/MC16S	12.1(5)pokemon	A0				
CW16	DLIN161	CM	D1.0	Dlink	DCM100	4.4270	3.2				
CW16	ELSA161	CM	D1.0	Elsa	204	1.30	G				
CW16	NORT161	CM	D1.0	Nortel Networks	CM220	2.4.1	1.4			Ambit	
CW16	0RDEL161	CMTS	D1.0	RiverDelta	BSR64000	00.01.00.BA	CHS-0001-02				
CW16	TOSH161	CM	D1.0	Toshiba	DAZ8813	1.7.007	6.62				
CW16	ZOOM161	CM	D1.0	Zoom	5031	2.0.42.70	029301				
CW15	3COM151	CM	D1.0	3Com	3CR29223(USB)	1.10	2.00				
CW15	AMBI151	CM	D1.0	Ambit	60194E	2.2.7	1.4				
CW15	ARRI151	CM	D1.0	Arris	CM200R	ST1.08	25			Thomson	
CW15	ASKE151	CM	D1.0	Askey Computer Corp.	RT080	1.10.0	8.0				
CW15	CISS151	CM	D1.0	CIS	WS-CM30EDTE	v2.14	1.0				
CW15	0CISC151	CMTS	D1.0	Cisco	UBR 7200 VXR	12.1(2)EC1	A0				
CW15	CISC151	CM	D1.0	Cisco	UBR905	Ubr925-klk2o3sv4y5-mz	A0				
CW15	CMT0151	CM	D1.0	Com21	DP1110	2.1.0.100	6				
CW15	LUCE151	CM	D1.0	DeltaKabel	Deomos 38-033	V2.91.0	v8.0			Aske131	
CW15	ELSA151	CM	D1.0	Elsa	204	1.18	E				
CW15	FUTU152	CM	D1.0	Future Networks	FN110C	V2.15	V1.C				
CW15	MASP151	CM	D1.0	Maspro	77TCM2	V1.0	V1.C				
CW15	0MOTO151	CMTS	D1.0	Motorola	DCM 2000 475390-001-00	1.0	475995-001-00 Rev 01				
CW15	MOTO152	CM	D1.0	Motorola	SB3100 Rev C	Rev v3.2.9	Rev C				
CW15	NETS151	CM	D1.0	Net & Sys	MNG-1000	2.20d	1.03				
CW15	OLEE151	CM	D1.0	OL'E Communications	HC1001	1.0.3657	01				
CW15	0RDEL151	CMTS	D1.0	RiverDelta	BSR1000	2.1.9	BSR 1000				
CW15	ORSTN151	CMTS	D1.0	RiverStone	RS8000	6.1.0.1	Chassis Rev B CMTS Model Rev 02				
CW15	SAEJ151	CM	D1.0	Saejin	SC-5100E	1.13	1.2				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW15	THOM151	CM	D1.0	Technicolor	DCM235/235R(USB)	ST1.08	25				Technicolor formerly known as Thomson
CW15	OTERA151	CMTS	D1.0	Terayon	Teralink 2000 TLL-CMTS41A	6.1	Chassis: revB, CMTS: Rev. 2				
CW15	TERA151	CM	D1.0	Terayon	TJ110/ECM110	1.7.6	6.12				
CW15	TERA152	CM	D1.0	Terayon	TJ210/ECM210(USB)	1.7.6	6.62				
CW15	TERA153	CM	D1.0	Terayon	TCM310	0036-58	D				
CW15	TOSH152	CM	D1.0	Toshiba	PCX1100 DAZ8811	1.7.006	6.12				
CW15	TOSH153	CM	D1.0	Toshiba	PCX1100U DAZ8813(USB)	1.7.006	6.62				
CW14	AMBI141	CM	D1.0	Ambit	60098U	2.0.5	2.0				
CW14	AMBI142	CM	D1.0	Ambit	60098E	2.0.13	1.3				
CW14	0ARRI142	CMTS	D1.0	Arris	CMTS-1000	3.2.1	Rev 08				
CW14	ARRI141	CM	D1.0	Arris	CM200U	RCA Broadband	ST 5.14			RCA	
CW14	ASUS141	CM	D1.0	Asustek	ACM6000EB	2.3	1.3				
CW14	0CISC141	CMTS	D1.0	Cisco	UBR 7200 VXR	12.0(11)SC	A0				
CW14	CMTO141	CM	D1.0	Com21	DP121	1.6.19	6.6			TurboNet Communications	
CW14	DXAN141	CM	D1.0	DX Antennae	DAZ8811	1.7.003	6.11			TOSH131	
CW14	DLIN141	CM	D1.0	Dlink	DCM100	0.44.32.52	Rev 2.3			PowerCom	
CW14	ERIC141	CM	D1.0	Ericsson	HM200c	Rev R1D	Rev. R2B				
CW14	ERIC142	CM	D1.0	Ericsson	HM200c	Rev R1E	Rev R2B				
CW14	GVCC141	CM	D1.0	GVC	CMI-004/CON	Rev 1.44.32.52	Rev 31				
CW14	0MOTO142	CMTS	D1.0	Motorola	MMLN 4004D	5.2	Engine, MVME2306-900 MRX, 74267G01, Rev C				
CW14	MOTO141	CM	D1.0	Motorola	SB3100 Rev D	Rev v3.2.6	Rev D				
CW14	MOTO143	CM	D1.0	Motorola	SB3100 Rev C	Rev v3.2.6	Rev C				
CW14	POWE141	CM	D1.0	Powercom	PCR2600	0.44.32.51	Rev 2.3				
CW14	SAMS141	CM	D1.0	Samsung Electronics	SCM-110R Ether	Rev 2.0.2	Rev 11.10				
CW14	THOM141	CM	D1.0	Technicolor	DCM 225	Ver 5.14	Ver 25				Technicolor formerly known as Thomson
CW14	TERA141	CM	D1.0	Terayon	ECM 210	Rev 1.6.19	Rev 6.6			TurboNet	
CW14	ZOOM141	CM	D1.0	Zoom	0110-Z5001-02-00-00	1.44.32.52	0295-01				
CW14	ZOOM142	CM	D1.0	Zoom	011-Z5011-02-00-0001	0.44.32.52	0293-01C				
CW13	03COM134	CMTS	D1.0	3Com	80-000971-01	3.61.48-1	Rev 1.0				
CW13	03COM135	CMTS	D1.0	3Com	8R-003678-10	4.4.18	Rev B				
CW13	3COM131	CM	D1.0	3Com	3CR29210	3.1.0	B.2				
CW13	3COM132	CM	D1.0	3Com	3CR29220	1.04	2.00				
CW13	3COM133	CM	D1.0	3Com	3CR29220	1.0.4	2.00				
CW13	ALCA131	CM	D1.0	Alcatel	uM141	1.7.3	6.10				
CW13	ASKE131	CM	D1.0	Askey Computer Corp.	CME033	V2.91.0	v8.0				
CW13	0BASS131	CMTS	D1.0	BAS	Cuda	0.1.58	D				
CW13	BEST131	CM	D1.0	BestData	CMX110	1.7.3	6.10				
CW13	CISC131	CM	D1.0	Cisco	UBR924	ubr920-k1y5-mz.1208TLN	A0				
CW13	FUTU131	CM	D1.0	Future Networks	100L	v2.13	v2.2				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW13	FUTU132	CM	D1.0	Future Networks	110L	v2.13	v1.0				
CW13	GVCC131	CM	D1.0	GVC	CMX-SO	3.10	B				
CW13	JOOH131	CM	D1.0	JooHong	Superlink 2000	1.7.3	6.1				
CW13	MOTO133	CM	D1.0	Motorola	SB3100 Rev C	v3.2.1	Rev C				
CW13	NETA131	CM	D1.0	Netgame	Phazer	2.80	6.0			ASKE121	
CW13	NETG131	CM	D1.0	Netgear	CM201	2.80	6.0			ASKE121	
CW13	NORT131	CM	D1.0	Nortel Networks	CM115	V2.91.0	V8.0				
CW13	SOHO131	CM	D1.0	SOHOware	NSC200	1.7.3	6.10				
CW13	TOSH131	CM	D1.0	Toshiba	DAZ8811	1.7.003	6.11				
CW13	TOSH132	CM	D1.0	Toshiba	DAZ8813	1.6.018	6.6				
CW13	ZYXE131	CM	D1.0	Zyxel	941	V2.4	Zygate CM V1.58				
CW12	3COM121	CM	D1.0	3Com	2940	2.03	L3				
CW12	ARRI121	CM	D1.0	Arris	CM200	ST 4.06	V24				
CW12	ARRI122	CM	D1.0	Arris	CM200	ST 5.05	V25				
CW12	ASKE121	CM	D1.0	Askey Computer Corp.	CME030	v2.80	v6.0				
CW12	CMTO123	CM	D1.0	Com21	DP111	1.6.16	6.1				
CW12	DASS121	CM	D1.0	Dassault	WD020	v2.80	v6.0				
CW12	HIGH121	CM	D1.0	HighSpeed Surfing	SM100	1.6.16	6.1			TURB121	
CW12	MOTO121	CM	D1.0	Motorola	MLN6200A	1.0CL08	75087G01				
CW12	MOTO122	CM	D1.0	Motorola	MMLN3150A	2.0.0t51	74362G01				
CW12	THOM121	CM	D1.0	Technicolor	DCM215	ST5.05	V24				Technicolor formerly known as Thomson
CW12	THOM122	CM	D1.0	Technicolor	DCM215	ST4.0b	V24				Technicolor formerly known as Thomson
CW12	THOM123	CM	D1.0	Technicolor	DCM225	ST5.05	V25				Technicolor formerly known as Thomson
CW12	TERA121	CM	D1.0	Terayon	ECM100	1.6.16	6.1				
CW12	TERA122	CM	D1.0	Terayon	ECM110	1.6.16	5.4				
CW12	TOSH121	CM	D1.0	Toshiba	DAZ8811	1.7.002	6.1				
CW12	TOSH122	CM	D1.0	Toshiba	DAZ881	1.6.016	6.1				
CW12	TURB121	CM	D1.0	Turbocomm	CM110	1.6.16	6.1				
CW11	BEST111	CM	D1.0	BestData	CMX100	1.6.14	5.4				
CW11	0CISC111	CMTS	D1.0	Cisco	UBR7200	11.3(11a)NA1	A0				
CW11	CMTO111	CM	D1.0	Com21	CP3001	1.0.1.100	6500087 revSA				
CW11	CMTO112	CM	D1.0	Com21	CP3001	1.0.5.100	6500106revSS				
CW11	CMTO113	CM	D1.0	Com21	CP3001	1.1.0.100	6500106revSS				
CW11	CMTO114	CM	D1.0	Com21	DP101	1.6.14	5.40				
CW11	CMTO115	CM	D1.0	Com21	DP101	1.6.14	5.4				
CW11	DXAN111	CM	D1.0	DX Antennae	DAZ8801D	1.6.003	5.21			TOSH092	
CW11	GENE111	CM	D1.0	General Instruments	SB3100A	v3.0.7	-002RevA				
CW11	GENE112	CM	D1.0	General Instruments	SB3100B	v3.0.7	-001RevB				
CW11	THOM111	CM	D1.0	Technicolor	DCM 205	ST 1.10	ver 16				Technicolor formerly known as Thomson
CW10	THOM101	CM	D1.0	Technicolor	DCM105	ST 20.5.3	HW Ver 12				Technicolor formerly known as Thomson
CW10	TERA101	CM	D1.0	Terayon	ECM100	1.6.9	5.4				
CW09	0ARRI091	CMTS	D1.0	Arris	DE3801E02	2.0.0	03				
CW09	ASKE091	CM	D1.0	Askey Computer Corp.	CME010	1.76	1.11				

Report run on 04/10/2012

CW	CL ID	Product Type	Spec Combo Certified As	Manufacturer	Model #	SW Version	HW Version	IPv6?	Interfaces	OEM Vendor ID	Public Comment
CW09	CISC091	CM	D1.0	Cisco	UBR904	11.3(9)NA ubr900-k1-y4-mz.cablelabs.13may99	A0				
CW09	OMOTO091	CMTS	D1.0	Motorola	MMLN004D	5.0.0t10	MAC, 74029G01, Rev A Engine, MVME3206-900 MTX-HI,				
CW09	MOTO091	CM	D1.0	Motorola	MMLN4004D	5.0t10p13b	MAC, 74029G01, Rev A Engine, MVME2306-900MTX-HI, 7				
CW09	PHIL091	CM	D1.0	Philips	PD10D	1.76	1.11				
CW09	SAMS091	CM	D1.0	Samsung Electronics	SCM-100R	1.1.76	1.2				
CW09	SONY091	CM	D1.0	Sony	CMR-1000	1.1 (0.76.1)	1.1				
CW09	TOSH092	CM	D1.0	Toshiba	PCX1000/DAZ8801F	Ver 1.6.003	Ver 5.21				
CW08	3COM081	CM	D1.0	3Com	3CR292-DE56	12.30	A01-3				
CW08	0ARRI081	CMTS	D1.0	Arris	DE3804E25	1.100.3	02				
CW08	GENE081	CM	D1.0	General Instruments	SB2100	V1.1.1	X3/0002				
CW07	0CISC071	CMTS	D1.0	Cisco	UBR7200	11.3(7)NA	A0				
CW07	THOM071	CM	D1.0	Technicolor	DCM 105	ST8.4	Pilot 3 c Rev's				Technicolor formerly known as Thomson
CW07	TOSH071	CM	D1.0	Toshiba	DAZ8801E	1.51k	5.2				